

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

Submit 1 Copy to Appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1503058380

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company <i>6137</i>	Contact Joah Weidemann
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-513-1528
Facility Name Cotton Draw Unit 113	Facility Type Oil

Surface Owner State	Mineral Owner State	API No 30-015-39517
----------------------------	----------------------------	----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	36	24S	31E	220	South	660	West	Eddy

Latitude: N 32.1672814 **Longitude:** W 103.7379624

NATURE OF RELEASE

Type of Release Spill Oil	Volume of Release 4 bbls	Volume Recovered 1.5 bbls
Source of Release Poly Flow Line	Date and Hour of Occurrence January 27, 2015 @ 2:30 am	Date and Hour of Discovery January 27, 2015 @ 2:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM Jim Amos OCD Thomas	
By Whom? Hubert Perry	Date and Hour January 27, 2015 @ 4:25 am and 4:32	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Ploy line from the Cotton Draw Unit 113 to the Cotton Draw 153 H was ran over by unknown subject and rocks punctured the flow line causing it to spew oil on to the pasture South West of Cotton Draw Unit 113. Enviro Clean was called out to recover the spill. They were able to recover 1.5 bbls of oil.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>1/30/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <u>corina.moya@dvn.com</u>	Conditions of Approval:	
Date: 1-30-2015 Phone: 575.746.5559	Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *2/28/15*

ERP-2774

Patterson, Heather, EMNRD

From: Moya, Corina <Corina.Moya@dvn.com>
Sent: Friday, January 30, 2015 10:46 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: Cotton Draw Unit 113-4bbls oil spill 1-27-2015
Attachments: Cotton Draw Unit 113 4 bbls oil spill 1-27-2015 Initial C-141.pdf.doc; Cotton Draw Unit 113 4 bbls oil spill 1-27-2015 pic 4 of 6.xlsm.JPG; Cotton Draw Unit 113 4 bbls oil spill 1-27-2015 pic 5 of 6.xlsm.JPG; Cotton Draw Unit 113 4 bbls oil spill 1-27-2015 pic 6 of 6.xlsm.JPG; Cotton Draw Unit 113 4 bbls oil spill 1-27-2015 pic 1 of 6.xlsm.JPG; Cotton Draw Unit 113 4 bbls oil spill 1-27-2015 pic 2 of 6.xlsm.JPG; Cotton Draw Unit 113 4 bbls oil spill 1-27-2015 pic 3 of 6.xlsm.JPG; Cotton Draw Unit 113 4 bbls oil spill 1-27-2015 GIS Mapping.pdf

Good morning,
Please see attached documents for the Cotton Draw 113 4bbls oil spill 1-27-2015.

Thank you,

Corina Moya
Field Admin Support
Production

Devon Energy Corporation
6488 Seven Rivers Hwy
Artesia, NM 88210
575-746-5559
corina.moya@dvn.com



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.