

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

JAN 30 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

FAB1503426369

**Release Notification and Corrective Action**

NAB1503426578

**OPERATOR**

Initial Report  Final Report

Name of Company Regency Gas	298751	Contact Rachel Johnson
Address P.O. Box 1226 Jal, NM 88252		Telephone No. 325-514-2636
Facility Name: Cal AB Launcher		Facility Type Pipeline launcher and receiver

Surface Owner NMBLM	Mineral Owner NMBLM	API No.
---------------------	---------------------	---------

**LOCATION OF RELEASE**

Unit Letter "A"	Section 8	Township 26S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy County
-----------------	-----------	--------------	-----------	---------------	------------------	---------------	----------------	--------------------

Latitude 32.002158 Longitude -103.973977

**NATURE OF RELEASE**


Type of Release: Condensate	Volume of Release: Unknown	Volume Recovered: 0
Source of Release:	Date and Hour of Occurrence: 1/10/15	Date and Hour of Discovery: 1/10/15
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken. \* On January 10, 2015 a vacuum truck driver attempted to load condensate into the Regency pipeline. Driver attached the hose to the wrong valve and sprayed condensate within a approx. 200ft radius. Driver made notifications to the appropriate Regency personnel. The affected area was not remediated in a timely manner; therefore creating a flow path crossing the Kinder Morgan ROW and finally reaching the ravine connecting to the Pecos River. Upon the notifications to Rachel Johnson, Regency Environmental Specialist for the area, Talon and a crew were dispatched. The affected soil has been sampled, area has been assessed, sumps and containments emptied, buoys placed in the ravine, and stockpile set on plastic and covered with plastic. Regency piping area has been benched and buoyed to avoid further runoff at this time.

Describe Area Affected and Cleanup Action Taken.\* Runoff from the piping ran into the ravine and is 1000ft from reaching the Pecos River. Buoys have been placed in the ravine to prevent further damage.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Rachel Johnson	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Rachel Johnson	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 2/2/15	Expiration Date:
E-mail Address: rachel.johnson@regencygas.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 1/30/15 Phone: 325-514-2636 (cell)	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: 2/2/15

2RP-2778

**Patterson, Heather, EMNRD**

---

**From:** Johnson, Rachel <Rachel.Johnson@regencygas.com>  
**Sent:** Friday, January 30, 2015 2:00 PM  
**To:** 'tgregsto@blm.gov'  
**Cc:** Bratcher, Mike, EMNRD; 'shitchcock@talonlpe.com'; 'Melissa Decker'; Patterson, Heather, EMNRD  
**Subject:** Cal AB launcher Initial C-141  
**Attachments:** Release Notification and Corrective Action.pdf

All-

Please find attached C-141.

Thank you for all your help. Have a good weekend.



**Rachel Johnson**  
**Regency Field Services**  
**Environmental Specialist**  
**Cell: 325-514-2636**

Private and confidential as detailed [here](#). If you cannot access hyperlink, please e-mail sender.