

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*New Operator: Breitburn Operating LP*

**OPERATOR**

Initial Report     Final Report

Name of Company Quantum Resources Management, LLC	Contact Garrett Newton	
Address 1905 West Sears Ave., Artesia, New Mexico 88210	Telephone No. 575-513-0230	
Facility Name State 647 AC 711 Water Flood Station #86	Facility Type WIW	
Surface Owner	Mineral Owner	Lease No. API # 30-015-02056

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	27	18S	28E	990'	South	330'	West	EDDY
Latitude 32.71420					Longitude -104.17128			

**NATURE OF RELEASE**

Type of Release Produced Waters	Volume of Release 25-30 bbls	Volume Recovered 20
Source of Release Flow line	Date and Hour of Occurrence 12/06/2010 AM	Date and Hour of Discovery 12/06/2010 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No    Not Required	If YES, To Whom? NMOCD/Mike Bratcher	
By Whom?	Date and Hour 12/06/2010 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The flow line at the State 647 AC 711 Water Flood Station ruptured. The flow line was taken out of service and then repaired. A vacuum truck was brought to the site and 20 bbls of produced water was recovered.

Describe Area Affected and Cleanup Action Taken.\*

The affected area was one hundred eleven feet (111') long by one hundred fifty-five feet (155') wide. Talon/LPE excavated the saturated soil from the impacted area to a depth of four feet (4') and transported to and NMOCD approved Solid Waste disposal facility. Talon/LPE backfilled the area with soil to match the surrounding terrain and the area seeded with an approved seed mixture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Garrett Newton</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Garrett Newton		Accepted for record <b>NMOCD</b>	
Title: Field Supervisor		Approval Date: 1/30/15	Expiration Date:
E-mail Address: gnewton@pvtnetworks.net		Conditions of Approval:	
Date: 5/18/2011	Phone: 575-513-0230	Attached <input type="checkbox"/>	

*Contamination left in place - to be addressed at time of site closure*

\* Attach Additional Sheets If Necessary