

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

State of New Mexico  
Energy Minerals and Natural Resources

JAN 22 2015 Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.  
**RECEIVED**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**fAB1503629448**      **Release Notification and Corrective Action**  
**1AB1503629550**      **OPERATOR**       Initial Report       Final Report

Name of Company <b>Enterprise Field Services LLC 1000347</b>	Contact <b>Dina Babinski</b>
Address <b>PO Box 4324, Houston TX 77210</b>	Telephone No. <b>210-528-3824</b>
Facility Name <b>Pipeline ROW, A-7 Gathering Lateral</b>	Facility Type <b>Gas Gathering Pipeline</b>
Surface Owner <b>Bureau of Land Management</b>	Mineral Owner <b>NA - Pipeline</b>
API No. <b>NA</b>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>P</b>	<b>8</b>	<b>22S</b>	<b>22E</b>	<b>480</b>	<b>North</b>	<b>300</b>	<b>West</b>	<b>Eddy</b>

Latitude **N 32.40067** Longitude **W -104.72015**

**NATURE OF RELEASE**

Type of Release <b>Natural Gas</b>	Volume of Release <b>105 MCF</b>	Volume Recovered <b>NA</b>
Source of Release <b>Pipeline Blowdown</b>	Date and Hour of Occurrence <b>1/15/2015 @ 15:20 MST</b>	Date and Hour of Discovery <b>1/15/2015 @ 15:20 MST</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

**Due to low temperatures, hydrates formed at various locations along the pipeline. A natural gas blowdown occurred as part of the hydrate removal activity. No liquids were produced during this event, and no pipeline repairs were necessary.**

Describe Area Affected and Cleanup Action Taken.\*

**No liquid spills occurred requiring any cleanup actions.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Jon E. Fields</b>	Approved by	Signed By: 
Title: <b>Director, Field Environmental</b>	Approval Date: <b>2/5/15</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>Snolan@eprod.com</b>	Conditions of Approval: <b>FINAL</b> ,ched <input type="checkbox"/>	
Date: <b>1/22/2015</b> Phone: <b>713-381-6684</b>		

\* Attach Additional Sheets If Necessary

2RP-2786



ENTERPRISE PRODUCTS PARTNERS L.P.  
ENTERPRISE PRODUCTS HOLDINGS LLC  
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

January 22, 2015

Via email

Mr. Mike Bratcher  
New Mexico Oil Conservation Division  
District 2 Office  
811 S. First St.  
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Field Services LLC  
Releases on Carlsbad Area Gathering Lines**

Dear Mr. Bratcher:

Enclosed, please find the required C-141 Form for unplanned blowdowns on our A-6 and A-7 Line in Eddy County on January 15, 2015. The pipeline required a blowdown during response to a line freeze. Enterprise is submitting this report form to satisfy the requirements of NMAC 19.15.29 for minor natural gas releases.

If you have any questions or need additional information, please contact Dina Babinski, our area Environmental Supervisor by phone at 210-528-3824 or via email at [djbabinski@eprod.com](mailto:djbabinski@eprod.com) or me directly at 713-318-6684.

Yours truly,

A handwritten signature in black ink, appearing to read "Jon Fields", written over a white background.

Jon Fields  
Sr. Director, Environmental

/sjn  
enclosure

**Bratcher, Mike, EMNRD**

---

**From:** Nolan, Shiver <SNolan@eprod.com>  
**Sent:** Thursday, January 22, 2015 3:03 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Babinski, Dina; DeLeon, Osman  
**Subject:** Eddy County A-6 & A-7 C-141 Reports  
**Attachments:** Eddy County A-6 and A-7 Line C-141 Release Report January 2015.pdf

Shiver J. Nolan  
Sr. Compliance Administrator  
Enterprise Products Operating LLC

---

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.