

**NM OIL CONSERVATION**

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

JAN 29 2015

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED** to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

#CLB0520730365  
 #AB1503643409  
 \* Per M. Bratcher OPERATOR  Initial Report  Final Report

Name of Company: Gibson Energy, LLC #34053	Contact: Bridget Sedlack
Address: 3819 Towne Crossing Blvd ste 100, Mesquite, TX	Telephone No.: 214-461-5563
Facility Name: Thomas Station	Facility Type: Crude Oil Storage Station

Surface Owner: Gibson Energy, LLC	Mineral Owner	API No.
-----------------------------------	---------------	---------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Fcct from the	North/South Line	Feet from the	East/West Line	County:
	23	23S	31E					Eddy

Latitude 32.286111 Longitude -103.741388

**NATURE OF RELEASE**

Type of Release: Crude Oil	Volume of Release: 11 bbls	Volume Recovered: 7 bbls
Source of Release: AST	Date and Hour of Occurrence: 1.28.15/Unknown	Date and Hour of Discovery: 1.28.15/ 8:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Notice was given to NMOCD the following morning. Put in touch with Mike Bratcher.	
By Whom? Bridget Sedlack	Date and Hour: 1.29.15/1:40am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A 1 inch corroded hole on the bull plug, located on the back bottom part of the north above ground storage tank (AST) was discovered.		
Describe Area Affected and Cleanup Action Taken.* Pulled all the oil out of the north tank and transferred it to the south tank which totaled to about 75 barrels. We were able to pick up about 7 barrels off the ground and put it in the operational tank. Have ~4 barrels in some areas that were too muddy to pick up. All of it is contained within secondary containment. The cleanup crew dug up all of the contaminated soil and they will haul it off proper disposal. After the repairs to the AST they will lay a new base. The dyke is lined so the oil could only penetrate to the lining.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bridget Sedlack	Approved by Environmental Specialist:	
Title: Environmental Manager-US Operations	Approval Date: 2/5/15	Expiration Date: N/A
E-mail Address: bridget.sedlack@gibsons.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 1.29.15 Phone: 214.461.5563	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: 2/5/15 2RP-2789

## Bratcher, Mike, EMNRD

---

**From:** Bridget Sedlack <bridget.sedlack@gibsons.com>  
**Sent:** Thursday, January 29, 2015 1:10 PM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** Thomas Station release C-141 Form  
**Attachments:** C-141 Form.Thomas Station.1.29.15.pdf

Hello Mr. Bratcher,

Attached please find the C-141 Form for our release at Thomas Station in Eddy County, NW.

Please let me know if you have any questions or comments.

Very Best,

Bridget Sedlack | Environmental Manager  
Gibson Energy, LLC | 3819 Towne Crossing, Ste 100 Mesquite, TX 75150  
p. 214-461-5563 | c. 214-236-6360 | f. 214-461-6102 | [bridget.sedlack@gibsons.com](mailto:bridget.sedlack@gibsons.com) | [www.gibsons.com](http://www.gibsons.com)



Information about the company can be found at <http://www.gibsons.com>.

This e-mail is confidential and may also be subject to legal privilege.

If you are not the intended recipient, please notify us by return e-mail; you may not copy, forward or use this e-mail for any purpose, nor disclose its contents to any other person.