

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1503649290 **OPERATOR** Initial Report Final Report

Name of Company: OXY Permian 192463	Contact: Christopher Jones
Address: 1502 W Commerce Dr.	Telephone No. 575-499-3337
Facility Name: Righthand Canyon 34 Fed Battery	Facility Type:

Surface Owner	Mineral Owner	API No. 30-015- 23289
---------------	---------------	----------------------------------

LOCATION OF RELEASE **32807**

Unit Letter	Section: 34	Township: 21S	Range 24E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
-------------	-------------	---------------	-----------	---------------	------------------	---------------	----------------	--------------

Latitude 32.40178 Longitude -104.5229

NATURE OF RELEASE

Type of Release: Water	Volume of Release: <u>8-10</u> BBLS	Volume Recovered: 0
Source of Release: Victollic	Date and Hour of Occurrence: 1/10/2015	Date and Hour of Discovery: 1/10/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT

Describe Cause of Problem and Remedial Action Taken.*

JAN 15 2015

4 inch Victollic on water line came loose

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

Safety & Environmental Solutions, Inc. will delineate the spill area and submit an appropriate work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US Date: 2015.01.15 10:10:14 -0600</small>	OIL CONSERVATION DIVISION	
Printed Name Christopher Jones:	Approved by Environmental Specialist: 	
Title:	Approval Date: <u>1/16/15</u>	Expiration Date: <u>NA</u>
E-mail Address: Christopher_jones@oxy.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date:	Phone: 575-499-3337	Attached <input type="checkbox"/>

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 3/5/15

* Attach Additional Sheets If Necessary

2 RP-2790

Patterson, Heather, EMNRD

From: Linsey Neeld <office2@sesi-nm.com>
Sent: Thursday, January 15, 2015 3:43 PM
To: Patterson, Heather, EMNRD
Cc: ballen@sesi-nm.com; scontreras@sesi-nm.com
Subject: C-141 for Righthand Canyon 34 Fed Battery
Attachments: Righthand Canyon 34 Fed Battery C-141 FORM.PDF

Good Afternoon Heather,

I left a message on your phone regarding this spill. If you have any questions or concerns please feel free to contact me.

Thank you,

Linsey Neeld

Administrative Assistant
Safety & Environmental Solutions, Inc.
Office: 575.397.0510
Fax: 575.393.4388
E-mail: office2@sesi-nm.com