

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

FEB 10 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

RECEIVED

Release Notification and Corrective Action

NAB1504155429

Name of Company Yates Petroleum Corporation <i>25575</i>		Contact Chase Settle	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address 104 S. 4 th Street, Artesia, NM 88210		Telephone No. 575-748-4171	
Facility Name State CO SWD System (West of Sagauo #4 Battery)		Facility Type Pipeline	
Surface Owner Fee	Mineral Owner	API No. 30-015-26420	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	14	20S	24E					Eddy

Latitude 32.56852 Longitude -104.56191

NATURE OF RELEASE

Type of Release Produced Water and Crude Oil Mix	Volume of Release Unknown	Volume Recovered 0
Source of Release 12" inch poly produced water line	Date and Hour of Occurrence 1/29/2015; a.m.	Date and Hour of Discovery 1/29/2015; a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Randy Dade.	
By Whom? Bob Asher	Date and Hour 1/30/2015; 2:28 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

During the course of pipeline maintenance, contamination was discovered on the end of a 12" poly produced water line.

Describe Area Affected and Cleanup Action Taken.* An approximate area of 50' X 50' was affected around the 12" poly produced water line. Impacted soils will be excavated and hauled to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: >100' (approximately 230', Section 14, T20S-R24E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Chase Settle	Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Agent	Approval Date: <i>2/10/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: csettle@yatespetroleum.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 02/10/2015 Phone: 575-748-4171	BMIT REMEDIATION PROPOSAL NO. <i>311015</i>	

DATE: 02/10/15

2RP-2803

Patterson, Heather, EMNRD

From: Chase Settle <CSettle@yatespetroleum.com>
Sent: Tuesday, February 10, 2015 9:55 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Bob Asher; Tanna Adams
Subject: C141 Initial- State CO SWD System (West of Saguaro #4 Battery)
Attachments: C141- Initial State CO SWD System (West of Saguaro #4 Battery).pdf

Categories: printed

Please find attached the C141- Initial for the below mentioned location.

**State CO SWD System (W of Saguaro # 4 Battery)
Section 14, T20S-R24E
Eddy County, New Mexico**

Thanks,

Chase Settle
**Environmental Regulatory Agent
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4171 (Office)
575-703-6537 (Cell)**

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Patterson, Heather, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Friday, January 30, 2015 2:28 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD
Cc: Amber Cannon; Chase Settle; Katie Parker; Tanna Adams
Subject: Release Notification (State CO SWD System)

Yates Petroleum Corporation is reporting a release at the following location (1/29/2015).

State CO SWD System (SW of Saguaro # 4 Battery)
Section 14, T20S-R24E
Eddy County, New Mexico

Released: Unknown amount of oil & produced water mix; Recovered: 0

Cause of release was from a 12" poly water line failure (approximately 0.4 miles SW of the Saguaro #4 Battery). A section of pipe was to be removed when discovered. Valves on line closed and necessary repairs made. Impacted soils being removed. A Form C-141 with complete information will be submitted.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
