

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

FEB 10 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

NAB150415L0159

Name of Company Yates Petroleum Corporation		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address 104 S. 4 <sup>th</sup> Street		Contact		
Facility Name Bodacious BSM Federal #1H		Telephone No. 575-748-1471		
Facility Type Battery				
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-41158		

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	I	26S	26E	510	South	660	West	Eddy

Latitude 32.06567 Longitude 104.25284

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 250 B/PW	Volume Recovered 0 B/PW
Source of Release 3 inch water line	Date and Hour of Occurrence 1/21/2015; AM	Date and Hour of Discovery 1/21/2015; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Bob Asher/Yates Petroleum Corporation	Date and Hour 1/22/2015; AM (Email)	<u>10:33am (Per e-mail)</u>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <u>AB</u>	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The 3 inch water line froze and broke, causing the release. Valves were closed to stop the leak.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 180' X 390'. Valves were closed to stop release. No produced water was recovered. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 20) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: < 25' (approximately 25', per the ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Asher	Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>2/10/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: February 10, 2015	Remediation per O.C.D. Rules & Guidelines	
Phone: 575-748-4217	SUBMIT REMEDIATION PROPOSAL NO	

Remediation per O.C.D. Rules & Guidelines

LATER THAN: 3/10/15

\* Attach Additional Sheets If Necessary

2RP-2802

**Patterson, Heather, EMNRD**

---

**From:** Tanna Adams <TCAadams@yatespetroleum.com>  
**Sent:** Tuesday, February 10, 2015 10:06 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Patterson, Heather, EMNRD; Bob Asher  
**Subject:** Bodacious BSM Federal #1H  
**Attachments:** Bodacious BSM Federal #1H Initial\_012115.pdf

Mr. Bratcher,

Please find attached the C141 Initial for the below listed location:

**Bodacious BSM Federal #1H**  
**30-015-41158**  
**Section 1,T26S-R26E**  
**510 FSL & 660 FWL**  
**Eddy County, New Mexico**

Thank you,

*Tanna Adams*  
*Yates Petroleum Corporation*  
*Environmental Tech*  
*Environmental Department*  
*TCAadams@yatespetroleum.com*

---

**This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.**

---

**Patterson, Heather, EMNRD**

---

**From:** Bob Asher <BobA@yatespetroleum.com>  
**Sent:** Thursday, January 22, 2015 10:33 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD;  
jamos@blm.gov; dwhitloc@blm.gov  
**Cc:** Amber Cannon; Chase Settle; Katie Parker; Tanna Adams  
**Subject:** Release Notification (Bodacious BSM Federal #1-H)

**Yates Petroleum Corporation is reporting a release at the following location (1/21/2015; approximately 11:30 AM).**

Bodacious BSM Federal #1-H  
30-015-41158  
510' FSL & 660' FWL  
Section 1, T26S-R26E  
Eddy County, New Mexico

**Released: Approximately 250 B/PW; Recovered: Approximately 0 B/PW**

Cause of release was from a frozen water line failure. Valves on line closed to stop release. The release was outside the battery. A Form C-141 with complete information will be submitted.

Thank you.

**Robert Asher**  
**NM Environmental Regulatory Supervisor**  
**Yates Petroleum Corporation**  
105 S. 4<sup>th</sup> Street  
Artesia, NM 88210  
575-748-4217 (Office)  
575-365-4021 (Cell)

---

**This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.**

---