

Received 2/19/15
 NMOC D Artesia

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company: OXY USA Limited Partnership		Contact: Chris Jones	
Address: 102 S. Main St. Carlsbad, NM 88220		Telephone No.: 575-628-4121	
Facility Name: Martha Creek Gas Com Battery		Facility Type: Battery	
Surface Owner: Federal		Mineral Owner:	API No.: Lease #: NM D-29301 2RP-2272

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	30	21S	24E					Eddy

Latitude 32.447610 N Longitude -104.5340 W

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 60 bbls	Volume Recovered: 30 bbls
Source of Release: Circulating Pump	Date and Hour of Occurrence 4/8/14	Date and Hour of Discovery 4/8/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher @ NMOC D - email Jennifer Van Curen @ BLM - email	
By Whom? Chris Jones	Date and Hour: 4/9/2014 9:35 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A 1-inch valve on the circulating pump was found leaking causing 60 barrels of oil to be released within the dike of the battery. The facility was shut-in, the pump repaired and put back into service. A vacuum truck was immediately called to the location and 30 barrels of oil was recovered. The area impacted was within the walls of the battery.**

Describe Area Affected and Cleanup Action Taken.* **Talon/LPE was contracted by Oxy for the correction of this release. Verbal permission was obtained from BLM and OCD to hand-excavate the impacted soil to the extent feasible within the battery to the top of rock. This was done and over 200 cubic yards of contaminated soil were disposed of at Lea Land. It would have been extremely difficult to do more work in the tank battery than was safely accomplished at that time - without total removal of the existing infrastructure. Talon personnel subsequently took a meeting with Mr. Bratcher and verbal permission to backfill the tank battery was obtained. We request that no further actions be required.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o=Oxy email=ckjones88@yahoo.com, c=US Date: 2015.02.19 10:13:38 -0600</small>	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: 	
Printed Name: Chris Jones	Approval Date: 2/24/15	Expiration Date: N/A
Title: HES Specialist	Conditions of Approval: Final	
E-mail Address: Christopher.Jones@oxy.com	Attached <input type="checkbox"/>	
Date: 2/18/2015 Phone: 575-628-4121		

* Attach Additional Sheets If Necessary

2RP-2272