

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAR 03 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1506434756 OPERATOR Initial Report Final Report

Name of Company Devon Energy Production	Contact Rudy Suniga
Address PO Box 250 Artesia NM 88211	Telephone No. 575-390-5435
Facility Name Strawberry 7 Fed Com #4	Facility Type Oil

Surface Owner BLM	Mineral Owner Federal	API No. 30-015-37258
-------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 7	Township 19S	Range 31E	Feet from the 340	North/South Line South	Feet from the 340	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: N 32°40'49.11"

Longitude: W 103°54'53.19"

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 6 bbls	Volume Recovered 3 bbls
Source of Release Frac tank load line valve was left open	Date and Hour of Occurrence December 29, 2014 12:00 am	Date and Hour of Discovery December 29, 2014 12:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Hubert Perry-Night Foreman/Ray Carter-Assistant Foreman/Scott Poe-EHS/OCD-voicemail/BLM-voicemail	
By Whom? Roy Ponce	Date and Hour December 29, 2014 12:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The night lease operator was called out to location by Black River Trucking employee. The previous Black River employee that had been out there left open the frac tank load line valve open. 6 barrels of produced water spilled on the location. 3 barrels of the produced water was recovered by Black River Trucking.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 3/5/15	Expiration Date: N/A
E-mail Address: corina.moya@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 29, 2014 Phone: 575.746.5559	MITIGATION per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary.

MITIGATION PROPOSAL NO. _____
LATER THAN: 4/5/15

2RP-2852