

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011.

MAR 05 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1506536208

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation <u>25575</u>		Contact
Address 104 S. 4 th Street		Telephone No. 575-748-1471
Facility Name Humidor BML State Com #5H		Facility Type Battery
Surface Owner State	Mineral Owner State	API No. 30-015-42755

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	26	24S	27E	2365	South	575	East	Eddy

Latitude 32.20188 Longitude 104.1544

NATURE OF RELEASE

Type of Release Drilling Mud	Volume of Release 200 B/DM	Volume Recovered 0 B/DM
Source of Release Mud suction pit	Date and Hour of Occurrence 2/19/2015; AM	Date and Hour of Discovery 2/19/2015; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 2/20/2015; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A mud tank was being moved by a forklift, the tank shifted and slide off and broke a 6" valve on the back of the suction pit, causing the drilling mud release.

Describe Area Affected and Cleanup Action Taken.*

The approximate area of the release was 20' x 100' (on the drilling pad) and 10' x 300' (off the drilling pad). Impacted soils will be excavated/hailed to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: 50-99' (approximately 50', per the ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>3/5/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	
Date: March 2, 2015	Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Phone: 575-748-4217	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: 4/5/15

* Attach Additional Sheets If Necessary

2RP-2861

Patterson, Heather, EMNRD

From: Tanna Adams <TCAadams@yatespetroleum.com>
Sent: Thursday, March 05, 2015 4:43 PM
To: Bratcher, Mike, EMNRD
Cc: Bob Asher; Patterson, Heather, EMNRD
Subject: Humidor BML State Com #5H
Attachments: Humidor BML State Com #5H_C141_Initial_021915.pdf

Mr. Bratcher,

Please find attached the signed C141 Initial for the below listed location:

**Humidor BML State Com #5H
30-015-42755
Section 26, R24S-R27E
2365 FSL & 575 FEL
Eddy County, New Mexico**

Thank you,

Tanna Adams

Yates Petroleum Corporation

Environmental Tech

Environmental Department

TCAadams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
