

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

MAR 6 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nA81506837856

OPERATOR

Initial Report Final Report

Name of Company: Oxy USA Inc. [16696]	Contact: Chris Jones
Address: 102 S. Main St. Carlsbad, NM 88220	Telephone No.: 575-628-4121
Facility Name: Cedar Canyon 28 Federal #4	Facility Type: Battery
Surface Owner: BLM	Mineral Owner: Federal
API No. 30-015-29118 Lease No: NM-64651	

LOCATION OF RELEASE

Unit Letter K	Section 28	Township 24S	Range 29E	Feet from the 1980'	North/South Line South	Feet from the 1980'	East/West Line West	County: Eddy
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	-------------------------------	-------------------------------	------------------------

Latitude 32.186554935 N Longitude -103.99165465

NATURE OF RELEASE

Type of Release: Mixed Fluids	Volume of Release 1 bbl Oil 14 bbls PW	Volume Recovered: Unknown
Source of Release: Tanks Overflowed	Date and Hour of Occurrence: 3/1/15	Date and Hour of Discovery 3/1/15
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The tanks overflowed due to human error. The load of water was not hauled off when it was suppose to causing a release of 1 barrel of oil and 14 barrels of produced water. A truck was called to the location to haul the load and an unknown number of barrels were recovered. Talon/LPE was contacted to do the initial site assessment and soil sampling activities.

Describe Area Affected and Cleanup Action Taken.* The area impact area on location affected was inside the berms of the facility. All fluids stay within the berms.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US; Date: 2015.03.06 08:18:56 -0600</small>	OIL CONSERVATION DIVISION	
Printed Name: Chris Jones	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: HES Specialist	Approval Date: 3/9/15	Expiration Date: N/A
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 3/5/2015	Phone: 575-628-4121	

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 4/9/15

* Attach Additional Sheets If Necessary

2RP-2868

Patterson, Heather, EMNRD

From: Kimberly M. Wilson <kwilson@talonlpe.com>
Sent: Friday, March 06, 2015 9:19 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos (jamos@blm.gov)
Cc: Hughes, Solomon; Robertson, Jeffery; Christopher_Jones@oxy.com; David Adkins
Subject: Signed C-141's
Attachments: Ceder Canyon 28 Federal #4 initial C141 DOR 3115.pdf; N Pure Gold A Fed #8 initial C141 DOR 22715.pdf; Winston SWD #4 initial C-141.pdf

Good Morning All,

Attached you will find the initial C-141's for the releases at the Cedar Canyon 28 Federal #4, DOR: 3/1/2015 , the North Pure Gold A Federal #8, DOR: 2/27/2015 and for the Winston SWD #4 DOR: 2/26/2015. Thanks.

Respectfully submitted,

Kimberly M. Wilson

Project Manager
Talon/LPE
408 West Texas Avenue
Artesia, New Mexico 88210
Office: 575.746.8768
Fax: 575.746.8905
Cell: 575.602.3826
Emergency: 866.742.0742
Email: kwilson@talonlpe.com
Web: www.talonlpe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist
Staples Foundation for Learning Hall of Fame Recipient:2010
ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006
Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007