

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
FEB 21 2013  
NMOC D ARTESIA

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

*nJMW 1305330428*

Name of Company	Linn Energy <i>269324</i>	Contact	Gary Wink
Address	2310 W. Bender, Hobbs, NM 88240	Telephone No.	575-738-1739 ext. 1218
Facility Name	J.L. Keel B #25	Facility Type	Injection Well
Surface Owner	BLM	Mineral Owner	Unknown
		Lease No.	30-015-05088

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	6	17S	31E					Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced Water	Volume of Release	Unknown	Volume Recovered	Unknown
Source of Release	Injection line	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	6/24/2011
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* Injection line ruptured and released fluids onto pasture land.					
Describe Area Affected and Cleanup Action Taken.* The leak affected 4,328 square feet of pasture. The impacted soils were scraped to 3' below ground surface and removed to a NMOCD approved disposal facility. Representative soil samples of the excavation bottom were submitted for laboratory confirmation. The excavation was backfilled with clean imported soil similar to that of the native terrain, and the site was contoured to the surrounding landscape with erosion controls. The site will be seeded with BLM seed mix #2 and #4.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

**OIL CONSERVATION DIVISION**

Signature: <i>Gary W. Wink</i>	Approved by District Supervisor: Signed By <i>Mike Brannon</i>	
Printed Name: Gary Wink	Approval Date: <b>FEB 22 2013</b>	Expiration Date:
Title: Production Foreman	Conditions of Approval: Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	
E-mail Address: <i>gawink@linneenergy.com</i>	Attached <input type="checkbox"/>	
Date: <i>2/20/13</i> Phone: (575) 738-1739 ext. 1218	<b>2RP-1560</b>	

\* Attach Additional Sheets If Necessary

*March 22, 2013*