

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1006 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAR 16 2015

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

NAB1507552530

OPERATOR

Initial Report Final Report

Name of Company: Clayton Williams	Contact: Luis Gonzalez
Address: 6 Desta Drive Suite 1100 Midland, TX 79705	Telephone No: 432-661-4708
Facility Name: State 20 E #2	Facility Type: Flowline

Surface Owner: State	Mineral Owner:	Lease No. 30-015-31051
----------------------	----------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section 20	Township 17S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy County
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	------------------------

Latitude 32.825409 Longitude -104.098243

NATURE OF RELEASE

Type of Release: Produced Water/Oil	Volume of Release: 170	Volume Recovered: 160(150PW/10Oil)
Source of Release: Flow Line Leak	Date/Hour of Occurrence: 3/11/15	Date/Hour of Discovery: 3/12/15
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD left message no call was given back. 3/13/2015 Called Heather Patterson.	
By Whom? Eric Garcia	Date and Hour: 3/12/15 11:30AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

The cause of the problem was a leak in the flow line from the well to the battery. The line was repaired. Also, vacuum truck removed the standing fluid. Approximately, 160 barrels were recovered, 150 barrels of PW and 10 barrels of oil. Hauled the fluid to the disposal. Finally, a crew installed a barb wire fence around the spill site. Pictures of the site were taken for future reports, and a one call was performed.

Describe Area Affected and Cleanup Action Taken.*

The area affected was pasture. The area measures approx. 10,000 sq ft. One call was performed on 3/12/15 by Republic Backhoe Service LLC. Once the one call clears a backhoe will be used to begin the delineation process. NMOCD will be notified to witness the sampling at the site. The contaminated soil will be hauled off and disposed at R360. Then clean soil will be hauled in to back fill the area. The remediation process will adhere to the NMOCD guideline for spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Dave Dunlap</i>	Approved by District Supervisor: <i>[Signature]</i>	
Printed Name: DAVE DUNLAP	Approval Date: 3/16/15	Expiration Date: N/A
Title: Prod Foreman	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
E-mail Address: ddunlap@claytonwilliams.com	SUBMIT REMEDIATION PROPOSAL NO	
Date: 3-15-15	Phone: 575 390 2062	

LATER THAN: 4/16/15

* Attach Additional Sheets If Necessary

22P-2887

Patterson, Heather, EMNRD

From: eric garcia <ericgarcia62@hotmail.com>
Sent: Monday, March 16, 2015 10:50 AM
To: Patterson, Heather, EMNRD; lgonzalez@claytonwilliams.com; eric garcia
Subject: State 20E #2 C-141
Attachments: State 20 E #2 C141 form.pdf

Heather,

The following attachment contains the C-141 for the Clayton Williams State 20E #2 spill. If you have any question call me at (575) 631-0131.

Eric Garcia

Republic Backhoe Service LLC.