

MAR 20 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1508234541

Name of Company: Devon Energy Production Co LP (6137)		Contact: Brian Kuh, Devon Completions Foreman	
Address: PO Box 250 Artesia, NM 88211		Telephone No. 575-616-1540	
Facility Name: Near Cotton Draw Unit 214H		Facility Type: Well location - OFF PAD	
Surface Owner: State	Mineral Owner: Federal	API No. 30-015-41537	

Initial Report Final Report

LOCATION OF RELEASE

Unit Letter C	Section 36	Township 24S	Range 31E	Feet from the 200	North/South Line North	Feet from the 1710	East/West Line West	County Eddy
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude: 32 deg 10' 49.931" N Longitude: 103 deg 44' 4.25" W

NATURE OF RELEASE

Type of Release: Produced Water from Trunk Line	Volume of Release: 6 bbls	Volume Recovered: 1 bbl
Source of Release: Water transfer trunk line	Date and Hour of Occurrence: 3/18/2015, 2:45 PM	Date and Hour of Discovery: 3/18/2015, 2:45 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Artesia - Mike Bratcher BLM Carlsbad - Jim Amos	
By Whom? Brian Kuh, Completions Foreman	Date and Hour: 3/19/15, 8:30 AM - OCD phones out of order 3/20/15, 7:30 AM - voicemail to Mike Bratcher 3/19/15, 8:30 AM - voicemail to Jim Amos	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Bosque Supervisor turned on pump to send water to Cotton Draw Unit 214 Poseidon tank. When the water started flowing, the hose separated from the hammer union off of the trunk line causing the spill.

Describe Area Affected and Cleanup Action Taken.*
The spill traveled approximately 8 feet to the North, 8 feet to the East, 7 feet to the West, and 22 feet to the South of the point of release. A vacuum truck was used to clean up as much water as possible, approximately 1 barrel. Alfredo's was called in to take soil samples.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Denise Menoud</i>	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: Denise.Menoud@dvn.com	Approval Date: 3/23/15	Expiration Date: N/A
Date: 3/20/2014 Phone: 575-746-5544	Conditions of Approval:	Attached <input type="checkbox"/>

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 4/25/15

2RPT-2904

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Menoud, Denise <Denise.Menoud@dvn.com>
Sent: Friday, March 20, 2015 1:41 PM
To: Bratcher, Mike, EMNRD; jamos@blm.gov
Cc: Menoud, Denise; Kuh, Brian
Subject: C141 - Cotton Draw Unit 214H 3/18/15
Attachments: C141 and map Spill 6 BPW - Bosque 3_18_15 CDU 214H.pdf

Please see attached C141 and map of 6 BPW spill on the Cotton Draw Unit 214H on 3/18/2015.

Thanks!

Denise Menoud

Admin Field Support 4 / Completions
Devon Energy Production Co. LP/Artesia NM
Denise.Menoud@dvn.com
575-746-5544

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.