

**NM OIL CONSERVATION**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

ARTESIA DISTRICT

MAR 9 2015

RECEIVED

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

NAB1508333382

**OPERATOR**

Initial Report  Final Report

Name of Company	Tandem Energy Corporation	Contact	Ernie Sanchez
Address	2700 Post Oak Blvd. Ste. 1000 Houston, TX 77056	Telephone No.	575-703-6865
Facility Name	Turkey Track Bec. 3 Unit 14	Facility Type	
Surface Owner	State of NM	Mineral Owner	State of NM
		API No.	30-015-03550



**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	195	29E	660	South	1980	East	Eddy
				Latitude	32° 41' 9.15"N	Longitude	104° 3' 32.12"W	

**NATURE OF RELEASE**

Type of Release	Produce water w/minor TPH Component	Volume of Release	n/a	Volume Recovered	n/a
Source of Release		Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Ernie Sanchez	Date and Hour	3/3/2015 11:57am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
n/a					
Describe Cause of Problem and Remedial Action Taken.*					
Cold weather flowline popped a hole, pumper called in. Crew went to location - refuse poly line to stop leak. Shut in well due to weather.					
Describe Area Affected and Cleanup Action Taken.*					
Affected area in a T formation 100' X 60' - had backhoe block in area - called HSE personnel to take action... 1000' from nearest road.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	L. Kiki Lockett	Signed By:  Approved by Environmental Specialist:	
Title:	Regulatory Specialist	Approval Date:	3/24/15
E-mail Address:	kikil@t5energy.com	Expiration Date:	N/A
Date:	03/03/2015	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	713-987-7326	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 4/25/15**

2RD. 2912