

**NM OIL CONSERVATION**

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

MAR 23 2015

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**FAB1508435844 Release Notification and Corrective Action**

NAB1508436016

**OPERATOR**

Initial Report  Final Report

Name of Company <b>Enterprise Field Services LLC</b>	Contact <b>Dina Babinski</b>
Address <b>PO Box 4324, Houston TX 77210</b>	Telephone No. <b>210-528-3824</b>
Facility Name <b>Pipeline ROW, 1009 Gathering Lateral</b>	Facility Type <b>Gas Gathering Pipeline</b>
Surface Owner <b>Department of Energy</b>	Mineral Owner <b>NA - Pipeline</b>
API No. <b>NA</b>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	15	22S	31E	421	North	7	East	Eddy

Latitude N 32.392 Longitude W -103.770

**NATURE OF RELEASE**

Type of Release <b>Natural Gas, Pipeline Liquids</b>	Volume of Release <b>24 MCF, 10 bbl</b>	Volume Recovered <b>NA</b>
Source of Release <b>Pipeline Relief Valve</b>	Date and Hour of Occurrence <b>Unknown</b>	Date and Hour of Discovery <b>3/18/2015 @ 11:30 MDT</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mike Bratcher</b>	
By Whom? <b>Osman De Leon</b>	Date and Hour <b>3/18/2015 2:52 MDT</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A pipeline relief valve opened and spilled approximately 10 bbl pipeline liquid to the ground and oversprayed surrounding area. Neither the valve nor the pipeline were damaged during the event, and thus no repairs were required.

Describe Area Affected and Cleanup Action Taken.\*  
Contaminated area is being marked and soil sampling will be performed to determine extent of contamination in soil. Remediation activities will be selected based on the results of the sampling. Additional soil sampling will be performed once remediation is complete to confirm cleanup is complete.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jon Fields</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Jon Fields</b>	Approved by	Signed By <i>Mike Bratcher</i>
Title: <b>Director, Field Environmental</b>	Approval Date: <b>3/26/15</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>snolan@eprod.com</b>	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b>	
Date: <b>3-20-2015</b> Phone: <b>713-381-6595</b>	Attached <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: 4/25/15

2RD-2015

## Bratcher, Mike, EMNRD

---

**From:** Nolan, Shiver <SNolan@eprod.com>  
**Sent:** Friday, March 20, 2015 10:18 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Babinski, Dina  
**Subject:** C0141 1009 Gathering Lateral  
**Attachments:** Eddy County C-141 1009 Gathering Lateral (TBD) March 2015.pdf  
  
**Categories:** Red Category

Attached for your review and handling is a C-141. Should you need additional information, please contact Dina Babinski at 210-528-3824.

Shiver J. Nolan  
Sr. Compliance Administrator

---

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.