

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

APR 07 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

**NAB1509842223** OPERATOR  Initial Report  Final Report

<b>Name of Company</b> Devon Energy Production <b>U137</b>	<b>Contact</b> Rudy Zuniga
<b>Address</b> 6488 Seven Rivers Hwy Artesia, NM 88220	<b>Telephone No.</b> 575-390-5435
<b>Facility Name</b> Coral PWU 28 #4H	<b>Facility Type</b> Oil

<b>Surface Owner</b> State	<b>Mineral Owner</b> State	<b>API No.</b> 30-015-39328
----------------------------	----------------------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter P	Section 28	Township 19S	Range 29E	Feet from the 330	North/South Line S	Feet from the 990	East/West Line E	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-----------------------	----------------------	---------------------	----------------

Latitude: N 32°62'53.95"

Longitude: W 104°07'45.21"

**NATURE OF RELEASE**

<b>Type of Release</b> Spill Oil	<b>Volume of Release</b> 10bbls	<b>Volume Recovered</b> 10bbls
<b>Source of Release</b> A 1" line on the suction side of the circulating pump was left open.	<b>Date and Hour of Occurrence</b> 4/2/2015 @ 9:45 PM	<b>Date and Hour of Discovery</b> 4/2/2015 @ 9:45 PM
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> BLM Jim Amos	
<b>By Whom?</b> David Simmons	<b>Date and Hour</b> 4/3/2015 @ 2:40 AM	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse</b>	

**If a Watercourse was Impacted, Describe Fully.\***

**Describe Cause of Problem and Remedial Action Taken.\***

Lease Operator went out to the Coral PWU 28 #4H location a found a 10 bbl oil spill inside the containment. There was a 30x30 fine mist over spray into the pasture on the South, Southeast side of the tanks. Lease Operator walked around the battery to locate where the oil was coming from, and found that the 1" line on the suction side of the circulating pump was left open. The line is used to drain the pot that catches the fluid when priming the circulating pump. It was found that when the pump would shut off, the gravity would push the fluid into the pot and out in to the containment and it was determined that the cause of the over spray was that with the high wind today it must have carried some of the oil out to the pasture. Containment was checked for holes none were found.

**Describe Area Affected and Cleanup Action Taken.\***

The 1" valve was closed and Basic Trucking recovered all 10 bbls from containment but 30x30 fine mist was not recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Corina Moya	Signed By <i>Mike Swanson</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: corina.moya@dvn.com	Approval Date: 4/8/15	Expiration Date: NIA
Date: 4/6/2015 Phone: 575.746.5559	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO**

LATER THAN: 5/8/15

2RP-2936

## Bratcher, Mike, EMNRD

---

**From:** Moya, Corina <Corina.Moya@dvn.com>  
**Sent:** Tuesday, April 07, 2015 3:20 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Subject:** Coral PWU  
**Attachments:** Coral Pwu 28 #4H 10 bbl oil spill 4.2.2015 Gis Mapping.docx; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 C-141.doc; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 10 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 11 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 12 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 13 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 14 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 15 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 16 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 17 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 1 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 2 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 3 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 4 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 5 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 6 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 7 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 8 of 17.JPG; Coral PWU 28 # 4H 10 bbl oil spill 4.2.2015 pic 9 of 17.JPG

Please see the attached information on incident at Coral PWU 28 #4H 10 bbl oil spill on 4.2.2015

Thank you,

**Corina Moya**  
Field Admin Support  
Production  
B Schedule

**Devon Energy Corporation**  
PO Box 250  
Artesia, NM 88211  
575 746 5559



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.