

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **NM OIL CONSERVATION**
Energy Minerals and Natural Resources ARTESIA DISTRICT
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

APR 06 2015
to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1509855020

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SRO State Unit Com #13H	Facility Type: Well

Surface Owner: State	Mineral Owner: State	API No. 30-015-37427
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 15	Township 26S	Range 28E	Feet from the 660	North/South Line North	Feet from the 330'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.0479055939123 Longitude -104.082877725172

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20 bbls PW	Volume Recovered: 15 bbls PW
Source of Release: 4" Poly Flowline	Date and Hour of Occurrence: 3/19/2015 1:00 pm	Date and Hour of Discovery: 3/19/2015 1:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
4" Poly connection on a flowline between two wells started to leak due to corrosion. Vacuum trucks were dispatched to the standing fluid and repairs were made.

Describe Area Affected and Cleanup Action Taken.*
The impacted area is approximately 40' x 20' in the pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 4/8/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: April 6, 2015 Phone: 575-748-6940	LATER THAN: 5/8/15	

* Attach Additional Sheets If Necessary

2RP-2938

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Monday, April 06, 2015 5:34 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: (Notification/C-141 Initial) SRO State Com #13H (30-015-37427)
Attachments: 3-19-15 SRO State Com #13H (FL) Initial.pdf

Categories: printed

Mr. Bratcher,

COG Operating LLC is reporting a release at the SRO State Com #13H (30-015-37427)
Unit D Section 15, Township 26S Range 28E
The release occurred at 1:00 pm on 3/19/2015
Released: 20 bbls PW
Recovered: 15 bbls PW

This release was caused when a 4" poly connection on a flowline between two wells started to leak due to corrosion. The site is being evaluated for clean-up. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,
Amanda Trujillo
Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.