

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
JUN 13 2011  
NMOCD ARTESIA

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GJ West Coop Unit #210 Tank Battery	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner	Lease No. API# 30-015-36703
---------------	-------	---------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	16	17S	29E					Eddy

Latitude 32 50.318 Longitude 104 04.987

**NATURE OF RELEASE**

Type of Release	Oil	Volume of Release	15bbls	Volume Recovered	0bbls
Source of Release	Oil Tank	Date and Hour of Occurrence	06/19/2010	Date and Hour of Discovery	06/19/2010 7:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Oil tank overflowed because oil did not equalize at the same rate as it was being produced. This problem has been corrected.

Describe Area Affected and Cleanup Action Taken.\*

Initially we released 15bbls out of the oil tank and into the lined facility. All released oil was contained inside the firewalls. The tank battery has been cleaned, the contaminated gravel has been removed, and fresh gravel has been added to the tank battery. (The closest well location to the tank battery is the GJ West Coop # 210, Unit C, Sec.16-T17S-R29E, 990 FNL 1650 FWL, Eddy County, NM, 32.8391 - 104.08307, API# 30-015-36703)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 	Approved by District Supervisor: 	
Printed Name: Josh Russo	Approval Date: 4/15/15	Expiration Date: N/A
Title: HSE Coordinator	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
E-mail Address: jrusso@conchoresources.com	Date: 06/13/2011	Phone: 432-212-2399

\* Attach Additional Sheets If Necessary

2PP-527

**Bratcher, Mike, EMNRD**

---

**From:** Joshua Russo [jrusso@conchoresources.com]  
**Sent:** Monday, June 13, 2011 2:27 PM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** Final C-141 Report - GJ WEST COOP UNIT #210 TB  
**Attachments:** GJ WEST COOP UNIT #210 TANK BATTERY -- 06-16-2010.pdf

Mr. Bratcher,

Please see attached the C-141 Final Report for a release that occurred at the GJ WEST COOP UNIT #210 TANK BATTERY on 06/16/2010. The battery was cleaned up last year shortly after the release date and I wanted to send you a final report for your records.

Thank you,

**Joshua Russo**

HSE Coordinator  
550 W. Texas Ave, Suite 100  
Midland, Texas 79701  
Phone: (432) 683-7443  
Cell: (432) 212-2399  
[jrusso@conchoresources.com](mailto:jrusso@conchoresources.com)



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.