

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Thursday, January 10, 2013 1:05 PM
To: 'Cliff P. Brunson'
Cc: C J Summers; Ken Swinney; Jennifer Gilkey; Kathy Purvis
Subject: RE: Oxy McCall #2 Battery

Reference: OXY USA * McCall 2 Battery * 30-015-29447 * M-24-18s-26e * Eddy County, New Mexico
NMOCD Tracking Number: 2RP-882 * Date of release: 7/1/11

Cliff,

Your proposal for remediation of the above referenced release is approved. Please contact me to discuss the results of confirmation samples prior to backfill, otherwise, proceed on your schedule.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, please contact me.

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Cliff P. Brunson [<mailto:cbrunson@bbcinternational.com>]
Sent: Monday, December 17, 2012 7:19 PM
To: Bratcher, Mike, EMNRD
Cc: C J Summers; Ken Swinney; Jennifer Gilkey; Kathy Purvis
Subject: Oxy McCall #2 Battery

Mike,

This e-mail is to confirm our discussion on December 17, 2012 concerning the remediation plan for the release that occurred at the Oxy McCall #2 Battery. I have attached the site drawing and the summary of the laboratory data we reviewed during our discussion for your files. As agreed, Oxy will surface scrape in the areas covered by SP1, SP2, SP3, and SP4 and will excavate to 3 feet in depth in the areas covered by SP5 and SP6 as depicted on the attached site diagram. A composite confirmation sample will be taken from the surface scraped area and bottom confirmation sample will be taken from the 3 foot excavated area. These samples will be analyzed for TPH and BTEX. The excavation will then be backfilled with clean soil. The depth to groundwater in this area is approximately 50 feet.

If you would please reply back via e-mail with your concurrence of this remediation plan, it would be greatly appreciated.

Oxy and I thank you for your assistance in handling this matter.

Thanks, Cliff

Cliff P. Brunson, CEI, CRS
President
BBC International, Inc.
World-Wide Environmental Specialists
Mailing Address:
P. O. Box 805
Hobbs, NM 88241-0805 USA
Shipping Address:
1324 W. Marland St.
Hobbs, NM 88240 USA
Phone: (575) 397-6388
Fax: (575) 397-0397
E-Mail: cbrunson@bbcinternational.com

Confidentiality Notice: This electronic transmission (and any attached documents) is intended only for the person(s) to whom it is addressed and may contain information that is privileged, confidential, or otherwise protected from disclosure. If you have received this transmission in error, please immediately notify the sender by e-mail or by telephone call to (575) 397-6388 for handling instructions. Any disclosure or distribution of the contents of this transmission by anyone other than the named recipient(s) is strictly prohibited.

Bratcher, Mike, EMNRD

From: Microsoft Outlook
To: Cliff P. Brunson; C J Summers; Ken Swinney; Jennifer Gilkey; Kathy Purvis
Sent: Thursday, January 10, 2013 1:05 PM
Subject: Relayed: RE: Oxy McCall #2 Battery

Delivery to these recipients or groups is complete, but no delivery notification was sent by the destination server:

[Cliff P. Brunson \(cbrunson@bbcinternational.com\)](mailto:cbrunson@bbcinternational.com)

[C J Summers \(Chancey Summers@oxy.com\)](mailto:Chancey_Summers@oxy.com)

[Ken Swinney \(kswinney@bbcinternational.com\)](mailto:kswinney@bbcinternational.com)

[Jennifer Gilkey \(jgilkey@bbcinternational.com\)](mailto:jgilkey@bbcinternational.com)

[Kathy Purvis \(kathy@bbcinternational.com\)](mailto:kathy@bbcinternational.com)

Subject: RE: Oxy McCall #2 Battery