

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

FAB1432841543 Release Notification and Corrective Action

NAB1511943117

OPERATOR Initial Report Final Report

Name of Company	<i>Enterprise Field Services LLC</i>	Contact	<i>Jim Heap</i>
	<i>PO Box 4324, Houston, TX 77252</i>	Telephone No.	<i>432-686-5404</i>
Facility Name	<i>Pipeline ROW, 30137 Gathering Lateral</i>	Facility Type:	<i>Gas Gathering Pipeline</i>
Surface Owner	<i>Multiple Producers, BLM</i>	Mineral Owner	<i>NA</i>
		Lease No.	<i>NA</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<i>13</i>	<i>19S</i>	<i>28E</i>					<i>Eddy</i>

Latitude: *N 32.653805* Longitude: *W -104.145020*

NATURE OF RELEASE

Type of Release	<i>Natural Gas</i>	Volume of Release:	<i>472 MCF</i>	Volume Recovered	<i>0</i>
Source of Release	<i>Line blow-down for maintenance.</i>	Date and Hour of Occurrence	<i>02/14/2014 @ 16:50 MST (start)</i>	Date and Hour of Discovery	<i>02/14/2014 @ 20:30 MST (end)</i>
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	<i>Mike Bratcher, District 2</i>		
By Whom?	<i>Jim Heap</i>	Date and Hour	<i>02/15/2014 @ 08:00 MST</i>		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
FEB 21 2014
NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

Blow-down to facilitate repair of hole in the pipe-wall; suspected corrosion fault.

Describe Area Affected and Cleanup Action Taken.*

Preparation for repairs.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Jon Fields</i>	OIL CONSERVATION DIVISION	
Printed Name:	<i>Jon E. Fields</i>	Approved by District Supervisor:	<i>Mike Bratcher</i>
Title:	<i>Director, Field Environmental</i>	Approval Date:	<i>4/29/15</i>
		Expiration Date:	<i>N/A</i>
E-mail Address:	<i>jefields@eprod.com</i>	Remediation per O.C.D. Rules & Guidelines	
Date:	<i>2-19-14</i>	SUBMIT REMEDIATION PROPOSAL NO	
Phone:	<i>713-381-6684</i>	LATER THAN: <i>5/29/15</i>	

Attached

* Attach Additional Sheets If Necessary

2RP-2974




ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

February 19, 2014

7011 2250 0002 3021 2204
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210



**RE: Form C-141 Report for Enterprise Field Services LLC
Releases on Carlsbad Area Gathering Lines**

Mr. Bratcher

Enclosed, please find the requisite C-141 Forms for the unplanned releases on our Eddy County gathering lines between February 13 and February 14, 2014. The releases were a combination of pipeline corrosion failure and hydrate blockage relief. This is sent pursuant to 29 (19.15.29) NMAC and as follow-up to verbal notifications made to your office by phone on February 15, 2014.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Regards,

Jon E. Fields
Director, Field Environmental

/sjn
attachments