

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Oil Conservation and Natural Resources

APR 29 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit a Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1512056213 **OPERATOR** Initial Report Final Report

Name of Company: OXY USA INC <i>1166916</i>	Contact: Chris Jones
Address: 102 S. Main St. Carlsbad, NM 88220	Telephone No.: 575-628-4121
Facility Name: State 2 #3 CTB	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No.: 30-015-26877
-----------------------------	----------------	------------------------------

LOCATION OF RELEASE

Unit Letter I	Section 2	Township 22S	Range 31E	Feet from the 2310'	North/South Line South	Feet from the 330'	East/West Line East	County Eddy
-------------------------	---------------------	------------------------	---------------------	-------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude **32.41591 N** Longitude **-103.74235 W**

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 90 bbls	Volume Recovered: 85 bbls
Source of Release: 2" Dump Line Corroded	Date and Hour of Occurrence 3/30/2015	Date and Hour of Discovery 3/30/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken: **A 2" dump line corroded causing a 90 barrel release within the containment of the facility. A vac truck was immediately call to the location and recovered 85 barrel of fluids.**

Describe Area Affected and Cleanup Action Taken.* The impacted area was inside the containment of the facility. **Talon/LPE has already performed site assessment and soil sampling activities. A work plan will be drafted by May 1, 2015**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Chris Jones Digitally signed by Chris Jones DN: cn=Chris Jones, o.ou, email=ckjones888@yahoo.co m, c=US Date: 2015.04.28 15:46:59 -05'00	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Chris Jones	Approval Date: 4/30/15	Expiration Date: N/A
Title: HES Specialist	Conditions of Approval:	
E-mail Address: Christopher.Jones@oxy.com	Attached <input type="checkbox"/>	
Date: 4/28/2015 Phone: 575-628-4121	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>5/30/15</u>	

* Attach Additional Sheets If Necessary

2RP-2975

Patterson, Heather, EMNRD

From: Kimberly M. Wilson <kwilson@talonlpe.com>
Sent: Wednesday, April 29, 2015 9:40 AM
To: Patterson, Heather, EMNRD; Bustamante, Amalia, EMNRD
Cc: Christopher_Jones@oxy.com; David Adkins
Subject: Oxy's Signed Initial C-141's
Attachments: Conoco 10 State #1 initial C-141.pdf; State 2 #3 CTB initial C-141.pdf; Two Marks 36 State 4 SWD C-141 initial.pdf

Good morning All,

Attached you will find a few signed initial C-141 for the above referenced release releases. My apologies for not getting some of these into you in a timely manner. I have had pneumonia for months. I had to be admitted to the ER. I should have everything caught up shortly, hopefully by the end of the week.

As you will see on the C-141's I will be drafting a work plan or have the location ready for further delineation.

Respectfully submitted,

Kimberly M. Wilson

Project Manager
Talon/LPE
408 West Texas Avenue
Artesia, New Mexico 88210
Office: 575.746.8768
Fax: 575.746.8905
Cell: 575.602.3826
Emergency: 866.742.0742
Email: kwilson@talonlpe.com
Web: www.talonlpe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist
Staples Foundation for Learning Hall of Fame Recipient: 2010
ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006
Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com
Sent: Thursday, April 09, 2015 8:15 AM
To: shughes@blm.gov; Bratcher, Mike, EMNRD
Cc: dadkins@talonlpe.com; kwilson@talonlpe.com

This is to inform you that Oxy had a leak at the A-OP State 2 3 CTB Battery on April 6 2015. The volume of the spill was 90 bbl oil in which 85 bbls were recovered. The leak was due to a 2" dump line on the test treater had some corrosion issues.

FROM CARLSBAD NM TAKE HWY 62180 EAST FOR 25 MILES AND CROSS RR TRACKS TO HALF WAY BAR JUST PAST BAR TURN SOUTH ON CR 29 FOR 3 MILES TO THE BIG TAN TANK WITH STAIRS, PLAINS EAST LIVINGTON RIDGE, TURN ON DIRT ROAD TO THE RIGHT THEN TAKE THE THIRD LEFT TURN AND GO .5 MILE TO BATTERY ON RIGHT SIDE OF ROAD

Chris Jones
HES OPS Specialist
OUSA USOp PR Del HES ENV
New Mexico
Cell 575-499-3337

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle