

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1512 754150

OPERATOR

Initial Report Final Report

Name XTO ENERGY INC.	Contact Sherry Pack
Address 200 N. LORAIN, STE. 800	Telephone No. 432.620.6709
Facility Name Nash 42	Facility Type Battery

Surface Owner XTO ENERGY INC.	Mineral Owner XTO ENERGY INC.	API No. 30-015-21277
---	---	--------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	13	23S	29E	1980	N	660	E	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Flaring	Volume of Release 12564 mcf	Volume Recovered
Source of Release casinghead gas	Date and Hour of Occurrence 4/17/15 6AM	Date and Hour of Discovery 4/17/15 6:00AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Heather Patterson	
By Whom? Patty Urias	Date and Hour 4/17/15 9:30AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
MAY 06 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully. *

Describe Cause of Problem and Remedial Action Taken. *
Enterprise plant shutdown causing us to flare as of 4/17/15. We stopped flaring 4/20/15 with a total of 96hrs and 12,564 mcf.

Describe Area Affected and Cleanup Action Taken. *
Flaring is being used to minimize emissions

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.

Signature: <i>Patty Urias</i>	OIL CONSERVATION DIVISION	
Printed Name: Patty	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Regulatory Analyst	Approval Date:	Expiration Date:
E-mail Address: patty_urias@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/5/2015	Phone: 432.620.4318	

* Attach Additional Sheets If Necessary

2RP- 2142

Patterson, Heather, EMNRD

From: Urias, Patty <Patty_Urias@xtoenergy.com>
Sent: Wednesday, May 06, 2015 7:31 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: RE: Nash 42 Flare Notice
Attachments: doc01747320150506082721.pdf

This flare event stopped on 4/20/15 – please see attached sundry.

Thanks,

Patty Urias

Regulatory Analyst

XTO Energy Inc.

432.620.4318

432.618.3530 efax

From: Urias, Patty
Sent: Friday, April 17, 2015 9:28 AM
To: mike.bratcher@state.nm.us; heather.patterson@state.nm.us
Cc: Midland Flare
Subject: Nash 42 Flare Notice

Nash 42 Battery went to flare yesterday at 6AM due to Enterprise Plant shutdown. Please see attached documentation and thanks,

Patty Urias

Regulatory Analyst

XTO Energy Inc.

432.620.4318

432.618.3530 efax