

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
State of New Mexico
Energy Minerals and Natural Resources
ARTESIA DISTRICT
Form C-141
Revised August 8, 2011
MAY 07 2015
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

FAB1434354066 Release Notification and Corrective Action

nAB1512856211

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: GJ West Coop Unit #92	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. N/A
----------------------	----------------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	17S	29E					Eddy

Latitude N32.80250 Longitude W104.07837

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 5 bbls	Volume Recovered: 0 bbls
Source of Release: Heater Treater Fire	Date and Hour of Occurrence: 3/30/2015 12:15 PM	Date and Hour of Discovery: 3/30/2015 12:15 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 3/31/2015 5:50 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
This release was caused when an electrical problem caused a fire in the heater treater. 5 bbls of oil was released as a result.

Describe Area Affected and Cleanup Action Taken.*
This release occurred and was contained in a lined facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 4/12/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: May 7, 2015	Phone: 575-748-6940	

* Attach Additional Sheets If Necessary

2RP-2990

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Thursday, May 07, 2015 5:31 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: (C-141 Initial-Final) GJ West Coop #92 Battery
Attachments: 3-30-2015 GJ West Coop Unit #92 (TB) Initial-Final.pdf

Mr. Bratcher,

Attached is a C-141 (Initial-Final) for your consideration. Please feel free to contact me if you have any questions or concerns.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Amanda Trujillo **On Behalf Of** HSE-Environmental-Journal
Sent: Tuesday, March 31, 2015 5:50 PM
To: 'Mike Bratcher'; 'Patterson, Heather, EMNRD'
Subject: (Notification) GJ West Coop #92 Battery

Mr. Bratcher,

COG Operating LLC is reporting a release and fire on the GJ West Coop #92 Battery
Unit J Section 28, Township 17S Range 29E
The release occurred at 5:32 pm on 11/20/2014
Released: 5 bbls Oil
Recovered: 0 bbls Oil

The release was caused by a heater treater. This release was contained within the lined facility. The site is being evaluated for clean-up and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

atrujillo@concho.com

2208 W. Main St.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.