

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

MAY 07 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1513152308

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production <i>6137</i>	Contact Roy White
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-513-1741
Facility Name Pure Grace State 1	Facility Type Gas

Surface Owner State	Mineral Owner State	API No. 30-015-24119
----------------------------	----------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	34	23S	27E	1980	South	1980	East	Eddy

Latitude: N 32°26"

Longitude: W 104°17'5"

NATURE OF RELEASE

Type of Release Spill water and oil	Volume of Release 90 bbls	Volume Recovered 90 bbls
Source of Release Spill was due to lightening catching the water and oil tanks on fire and causing the tops to blow off.	Date and Hour of Occurrence May 4, 2015	Date and Hour of Discovery May 4, 2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos at BLM	
By Whom? David Simmons Assistant Night Production Foreman	Date and Hour May 4, 2015 @ 10:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Lightning struck either the water tank or oil tank blowing the tops off of both tanks. The top of the water tanks was blown about 50 ft North West in to the pasture behind the battery, and the top of the oil tanks was blown about 15 ft to the South East of the front side of the battery. The water tank had burned to the ground leaving about a 3 ft height steel of what used to be the tank. The spill was contained inside the containment. Basic Energy Trucking recovered 70 bbls from containment and 20 bbls out of the oil tank due to the main way cover seal being melted from the heat of the fire. A total of 90 bbls were recovered.

Describe Area Affected and Cleanup Action Taken.*

All fluid stayed inside of containment and tank. Basic Energy Trucking recovered the 70 bbl spill and 20 bbls of oil from the oil tank. Tanks will be replaced at the locations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>5/11/15</i>	Expiration Date: <i>NIA</i>
E-mail Address: corina.moya@dvn.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 5.7.2015 Phone: 575.746.5559	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: *10/12/15*

2RP-2995

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Moya, Corina <Corina.Moya@dvn.com>
Sent: Thursday, May 07, 2015 2:10 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; Sol Hughes (shughes@blm.gov); Jeff Robertson (jrobertson@blm.gov)
Cc: Jim Amos (jamos@blm.gov)
Subject: Pure grace State 1 90 bbl water and oil spill 5.4.2015
Attachments: Pure Grace State 1_90 bbl water and oil spill 5.4.2015 pic 2 of 5.jpeg; Pure Grace State 1_90 bbl water and oil spill 5.4.2015 pic 3 of 5.jpeg; Pure Grace State 1_90 bbl water and oil spill 5.4.2015 pic 4 of 5.jpeg; Pure Grace State 1_90 bbl water and oil spill 5.4.2015 pic 5 of 5.jpeg; Pure Grace State 1_90 bbl water and oil spill 5.4.2015 C-141.doc; Pure Grace State 1_90 bbl water and oil spill 5.4.2015 pic 1 of 5.jpeg; Pure Grace State 1_90 bbl water and oil spill 5.4.2015 GIS Mapping2.docx

Good afternoon,

Please see the attached C-141 and pics of the incident at the Pure Grace State 1 that occurred on 5.4.2015

Thank you,

Corina Moya
Field Admin Support
Production
B Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 746 5559



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.