

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

MAY 08 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

nAB1513155433

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	25575	Contact Amber Cannon
Address 104 S. 4 th Street		Telephone No. 575-748-1471
Facility Name Harkey 35 State #1		Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-015-25812
------------------------	------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	35	24S	27E	2180	South	1980	East	Eddy

Latitude 32.17225 Longitude 104.15877

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30 B/PW	Volume Recovered 15 B/PW
Source of Release Production Tank	Date and Hour of Occurrence 4/21/2015; AM	Date and Hour of Discovery 4/21/2015; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 4/22/2015; AM (Email) ← 4/21/15 4:43pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The water pump failed and did not start, causing the produced water tank to overflow. Vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 15' X 15' inside and outside of the unlined berm. The water pump was started and vacuum trucks were called to recover the spill. Impacted soils will be excavated and hauled to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: 50-99' (approximately 60', Section 35, T24S-R27E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amber Cannon</i>	OIL CONSERVATION DIVISION	
Printed Name: Amber Cannon	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: NM Environmental Regulatory Agent	Approval Date: <u>5/11/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: ACannon@yatespetroleum.com	Conditions of Approval:	
Date: April 27, 2015	Remediation per O.C.D. Rules & Guidelines	
Phone: 575-748-4111	SUBMIT REMEDIATION PROPOSAL NO. <u>20P-2997</u>	

* Attach Additional Sheets If Necessary

LATER THAN: 6/12/15

20P-2997

Patterson, Heather, EMNRD

From: Amber Cannon <ACannon@yatespetroleum.com>
Sent: Friday, May 08, 2015 11:10 AM
To: Patterson, Heather, EMNRD
Subject: FW: Harkey 35 State #1 C141
Attachments: Harkey 35 State #1_C141_Initial_042115.pdf

Heather,

I was just looking for this on NMOCD online and couldn't find where NMOCD had processed it. So, I went back to this email that Tanna had sent and saw that you were left off of it.

Thanks,
Amber

From: Tanna Adams
Sent: Wednesday, April 29, 2015 3:27 PM
To: Mike Bratcher (mike.bratcher@state.nm.us)
Cc: Bob Asher; Amber Cannon; Katie Parker; idolly@slo.state.nm.us; mhagman@slo.state.nm.us; mnanranjo@slo.state.nm.us; dvstrang@slo.state.nm.us
Subject: Harkey 35 State #1 C141

Mr. Bratcher,

Please find attached the signed C141 Initial for the below listed location:

Harkey 35 State #1
30-015-25812
Section 35, T24S-R27E
2180 FLS & 1980 FEL
Eddy County, New Mexico

Thank you!

Tanna Adams
Yates Petroleum Corporation
Environmental Tech
Environmental Department
TCAdams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors

or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Patterson, Heather, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Tuesday, April 21, 2015 4:43 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD; NMSLO (Carlsbad/Ion Dolly); NMSLO (Hobbs/Mathew Hagman); Naranjo, Mark M.; NMSLO (Santa Fe/Dana Vackar Strang)
Cc: Amber Cannon; Chase Settle; Katie Parker; Tanna Adams
Subject: Release Notification (Harkey 35 State #1)

Yates Petroleum Corporation is reporting a release at the following location (4/21/2015, 9:00 AM).

Harkey 35 State #1
30-015-25812
2180 FSL & 1980 FEL
Section 35, T24S-R27E
Eddy County, New Mexico

Released: Approximately 30 B/PW; Recovered: In Process.

The above release was reported, caused by a pump failure. Any needed repairs are being made and vacuum truck(s) have been dispatched. **A Form C-141 with complete information will be submitted.**

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

Received
C-141
5/8/15
ZRP# 2997

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
