

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

MAY 11 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Release Notification and Corrective Action

NAB1513157754

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production LD137	Contact Rudy Zuniga, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-390-5435
Facility Name Arcturus 18 Fed 5H	Facility Type Oil
Surface Owner Federal	Mineral Owner Federal
API No. 30-015-41802	

LOCATION OF RELEASE

Unit Letter A	Section 18	Township 19S	Range 31E	Feet from the 845	North/South Line FNL	Feet from the 250	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.6653332°N

Longitude: 103.9008789°W

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 20bbls	Volume Recovered 20bbls
Source of Release H.F. back pressure valve	Date and Hour of Occurrence May 6, 2015 6:30 AM	Date and Hour of Discovery May 6, 2015 6:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson, BLM Mike Bratcher, OCD	
By Whom? Lynn Smith, Asst. Production Foreman	Date and Hour Jeff Robertson, BLM May 6, 2015 8:57 AM Mike Bratcher, OCD May 6, 2015 8:59 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
On May 6, 2015 6:30 AM the Lease Operator was contacted and told that the Arcturus 18 Fed 5H was leaking from the well head, upon Lease Operator's arrival to the location he discovered a H. F. back pressure valve had washed out releasing 20bbls of oil and produced water mix onto location.

Describe Area Affected and Cleanup Action Taken.*
The affected area was 48x85 with all fluids contained on location. Legendary Trucking recovered all 20bbls of oil and produced water mix and the contaminated dirt will be removed from location and replaced with fresh dirt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 5/11/15	Expiration Date: N/A
E-mail Address: Sheila.Fisher@dmv.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: _____ Phone: 575.748.1829	REMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 01/21/15

2RP-2998

Patterson, Heather, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Monday, May 11, 2015 10:03 AM
To: Jim Amos (jamos@blm.gov); jlrobertson@blm.gov; Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Harris, Jacqui
Subject: Arcturus 18 Fed 5H_20bbbls Oil PW mix release_5.6.15
Attachments: C-141_Arcturus 18 Fed 5H_20bbbl Oil PW mix release_5.6.15.doc; Arcturus 18 Fed 5H_20bbbl Oil PW mix release_GIS Image_5.6.15.Word.docx; Arcturus 18 Fed 5H_20bbbl Oil PW mix release_photo 1 of 2_5.6.15.jpeg; Arcturus 18 Fed 5H_20bbbl Oil PW mix release_photo 2 of 2_5.6.15.jpeg

Good Morning,

Attached please find the Initial C-141, GIS Image and photos for the 20bbbl Oil & PW mix release at the Arcturus 18 Fed 5H. Please note the blue square on the GIS image represents the approximate location for the Arcturus 18 Fed 5H.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.