

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SEP 26 2012

NMOCD ARTESIA

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR



☐ Initial Report ☒ Final Report

Name of Company Devon Energy	Contact Tracy Kidd	
Address P. O. Box 250 Artesia, NM 88211	Telephone No. 575-513-0628	
Facility Name: Snapping 2 State 4H	Facility Type Oil Well	
Surface Owner	Mineral Owner	API #: 30-015-39071 2RP-1280

LOCATION OF RELEASE

Unit Letter P	Section 2	Township 26S	Range 31E	Feet from the 330'	North/South Line South	Feet from the 735'	East/West Line East	County EDDY
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

NATURE OF RELEASE

Type of Release: Oil	Volume of Release - 20 bbls	Volume Recovered - 10 bbls
Source of Release: Overflow Tank	Date and Hour of Occurrence 8/22/12, 7:30 AM	Date and Hour of Discovery 8/22/12, 7:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD / Mike Bratcher	
By Whom? Daniel Suniga	Date and Hour: 8/22/12, 8:45 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* At the Snapping 2 State 4H battery, a miscommunication between two well watchmen led to the overflow of a frac tank. A vacuum truck was immediately called to location.		
Describe Area Affected and Cleanup Action Taken.* Banta was immediately contracted for the correction of this release. The impacted area from this release was excavated to a depth of 2-feet deep. Talon/LPE was contacted to do the analytical testing. The OCD gave permission to backfill the excavation on September 13, 2012. The excavation was backfilled to grade using new material and contoured to match the surrounding location.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Gracie Bustamante	Approved by District Supervisor: 	
Title: Admin Field Support	Approval Date: 9/23/12	Expiration Date: N/A
Date: 9/24/2012 Phone: 575-746-5561	Conditions of Approval: Final	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-1280