

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Oxy Permian LTD	Contact Dusty Wilson
Address 1017 W. Stanolind Rd, Hobbs NM	Telephone No. (575) 397-8247
Facility Name Winston Gas Com #4	Facility Type Production

Surface Owner BLM	Mineral Owner BLM	Lease No. 30-015-30337
-------------------	-------------------	------------------------

LOCATION OF RELEASE. API #30-015-28305

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	31	21S	24E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 16 bw	Volume Recovered 10 bw
Source of Release SWD pump failure	Date and Hour of Occurrence 08/18/2011	Date and Hour of Discovery: 08/18/2011

Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?
--	------------------

By Whom?	Date and Hour
----------	---------------


Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse
---	--

If a Watercourse was Impacted, Describe Fully.* N/A	<div style="border: 1px solid black; padding: 5px;"> <p>RECEIVED</p> <p>JAN 11 2012</p> <p>NMOCD ARTESIA</p> </div>
--	---

Describe Cause of Problem and Remedial Action Taken.*
Thrust chamber on SWD pump failed. All free fluids were recovered via Vac Truck. Remediation complete as described in the OCD and BLM approved remediation plans.

Describe Area Affected and Cleanup Action Taken.*
10 bw were recovered. Immediate/initial response was free-fluid recovery via vacuum truck. Clean up was performed by excavating the impacted soil and backfilling the site with clean soil. Confirmation sampling was performed and results were provided to the BLM and NMOCD. Closure was granted on 11/28/2011 by the BLM. Finalization approval was granted by the NMOCD on 11/22/2011.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dusty Wilson	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 1/24/15	Expiration Date: N/A
E-mail Address: Dusty_Wilson@oxy.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 12-17-2011	Phone: (575) 397-8210	

* Attach Additional Sheets If Necessary

22P-887