

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Oxy Permian LTD.	Contact: Dusty Wilson
Address: 1017 W. Stanolind Rd, Hobbs, NM	Telephone No. (575) 397-8247
Facility Name: Federal 26 #3	Facility Type: Production

Surface Owner: BLM	Mineral Owner: BLM	Lease No. 30-015-26788
--------------------	--------------------	------------------------

LOCATION OF RELEASE API #30-015-28305

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	26	22S	31E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Oil and Produced water	Volume of Release: 15 bo & 5 bw	Volume Recovered: none
Source of Release: Liner Separated	Date and Hour of Occurrence: 07/30/2011	Date and Hour of Discovery: 07/30/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? n/a	
By Whom? CJ Summers	Date and Hour: n/a	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	


RECEIVED
 JAN 11 2012
 NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Liner broker inside well head. No free liquids could be recovered. Remediation complete as described in the OCD and BLM approved remediation plans.

Describe Area Affected and Cleanup Action Taken.*
The liner inside the well head broker causing the release of oil and produced water to leak into location area. Cleanup was performed by excavating the impacted area and backfilling the site with clean soil. Confirmation sampling was performed and the results were provided to the BLM and NMOCD. Remediation approvals were provided by the OCD on 10/12/2011 and by the BLM on 10/24/2011.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dusty L. Wilson	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 4/24/15	Expiration Date: N/A
E-mail Address: Dusty_Wilson@oxy.com	Conditions of Approval: 	Attached <input type="checkbox"/>
Date: 1-4-12	Phone: 575-397-8210	

* Attach Additional Sheets If Necessary

2RP-883