

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

| | | | |
|-----------------|---------------------------------|---------------|-------------------|
| Name of Company | Oxy Permian Ltd. | Contact | CJ Summers |
| Address | 1017 W. Stanolind Rd, Hobbs, NM | Telephone No. | (575) 397-8216 |
| Facility Name | Cedar Canyon 28 Federal #4 | Facility Type | Gathering |
| Surface Owner | BLM | Mineral Owner | API# 30-015-29118 |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| K | 28 | 24S | 29E | 1980' | South | 1950' | West | Eddy |

Latitude N 32.18629° Longitude W 103.99155°

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|-------------------------------------|----------------------------|--------|
| Type of Release | Produced water | Volume of Release | 80 bbls | Volume Recovered | 0 bbls |
| Source of Release | Valve on suction line left open | Date and Hour of Occurrence | 08/14/2012 | Date and Hour of Discovery | |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Mike Bratcher- OCD; James Amos- BLM | | |
| By Whom? | Chancey Summers | Date and Hour | 08/14/2012 @ 12:58 pm | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

RECEIVED
 SEP 27 2013
 NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The valve on a 1" steel suction line between the triplex pump and tank was left open which caused 80 bbls of water to spill onto the ground. 0 bbls of water were recovered. The valve was closed to prevent further leaking.

Describe Area Affected and Cleanup Action Taken.*

The area affected by the 80 bbls leak is approximately 40' x 100'. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOCD via email on 01/24/2013 and approved by Jennifer Van Curen of the BLM via email on 03/25/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|---|----------------------------------|---|--|
| Signature: | <u>OIL CONSERVATION DIVISION</u> | | |
| Printed Name: Chancey Summers | Approved by District Supervisor: |  | |
| Title: HES Specialist | Approval Date: 5/5/15 | Expiration Date: N/A | |
| E-mail Address: Chancey.Summers@oxy.com | Conditions of Approval: Final | Attached <input type="checkbox"/> | |
| Date: 9/24/13 | Phone: (575) 397-8216 | | |

* Attach Additional Sheets If Necessary

2PP-1318