

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1514253266 OPERATOR Initial Report Final Report

Name of Company <i>Linn Operating Inc. 209324</i>	Contact E.L. Gonzales
Address 2130 W Bender Blvd Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name H.E. West B # 92	Facility Type Oil Producer
Surface Owner Federal	Mineral Owner
API No. 30-015-28538	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	09	17S	31E	1350	South	1440	East	Eddy

Latitude 32.8456 Longitude -103.87019

NATURE OF RELEASE

Type of Release Oil / Produce Water	Volume of Release 1 bbl / 1 bbl	Volume Recovered 1 bbl / 1 bbl
Source of Release Poly Pipeline	Date and Hour of Occurrence 05/11/2015	Date and Hour of Discovery 05/11/2015 2:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NM OIL CONSERVATION	
By Whom?	Date and Hour	ARTESIA DISTRICT
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. MAY 21 2015	

If a Watercourse was Impacted, Describe Fully.*
RECEIVED

Describe Cause of Problem and Remedial Action Taken.* Mario Garcia (432)202-4333 with M&G rental tools was avoiding driving through mud puddle in road and drove off road and over flow lines. Flow line on WB#92 was damaged releasing fluid on the road into a puddle of fresh water, adjacent shrubbery, and a small amount into the pasture. Total fluid released was approximately 2 bbl total fluid. Mario Garcia called in Double R trucking to pick up liquids and will accept full liability and cost for the spill. Manuel with BTS (575) 942-8307 repaired the line.

Describe Area Affected and Cleanup Action Taken.* Puddle was approx 30ft x 20ft, area affected in pasture was to the south approx. 2ft x 30ft. Michael Burton with DFSI (575)942-4115 will handle further assessment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: E.L. Gonzales	Approved by Environmental Specialist:	
Title: Production Supervisor	Approval Date: 5/22/15	Expiration Date: N/A
E-mail Address: elgonzales@linenergy.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: 05/12/2015	Phone: 505-504-8002	Attached <input type="checkbox"/>

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 05/22/15 **2RD-3012**

* Attach Additional Sheets If Necessary