

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

*Second*  
*5/15/15*  
*Artesia*  
*NMOCD*

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**FAB1514 737885**      **Release Notification and Corrective Action**      **AMENDED**  
**NAB1514 738018**      **OPERATOR**       Initial Report       Final Report

Name of Company	Plains Pipeline, LP <i>240911</i>	Contact	Camille Bryant
Address	2530 State Hwy. 214, Denver City, TX 79323	Telephone No.	(575) 441-1099
Facility Name	Palladium 7-1 4-Inch Poly	Facility Type	4-Inch Poly Pipeline

Surface Owner	BLM	Mineral Owner		Lease No.	
---------------	-----	---------------	--	-----------	--

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	5	24S	31E					Eddy

Latitude N 32.2519600° Longitude W 103.800570°

**NATURE OF RELEASE**

Type of Release	Crude Oil	Volume of Release	>5 bbls	Volume Recovered	0 bbls
Source of Release	4-Inch Poly Pipeline	Date and Hour of Occurrence	03/01/2013 @ 10:51	Date and Hour of Discovery	03/01/2013 @ 10:51
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* Pinhole developed in 4-inch poly pipeline. The pipeline was de-oiled and the damaged portion of the pipeline was replaced.

Describe Area Affected and Cleanup Action Taken. The release was initially believed to be 0.5 barrel; however, on delineation activities the release was amended to greater than five barrels and reported to the NMOCD and BLM. The visually impacted area measured approximately 100' x 60'. The impacted area will be remediated as per applicable NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Camille Bryant</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Camille Bryant	Approved by District Supervisor: <i>Hubert</i>	
Title: Remediation Coordinator	Approval Date: <i>5/26/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>cjbryant@paalp.com</i>	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/>	
Date: <i>5/16/2015</i> Phone: (575) 441-1099	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	
	<b>LATER THAN: <i>5/28/15</i></b>	

\* Attach Additional Sheets If Necessary

*2RP-3018*