

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company - <b>Devon Energy</b>	Contact - <b>Roy White, Foreman</b>
Address - <b>6488 Seven Rivers Hwy - PO Box 250</b>	Telephone No. - <b>575-513-1741</b>
Facility Name - <b>Cactus State No. 3</b>	Facility Type: <b>Oil Well</b>

Surface Owner	Mineral Owner	Lease No. <b>API # 30-015-27979 2RP-1045</b>
---------------	---------------	--

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	21S	26E	1900'	North	2145'	East	Eddy

Latitude 32.48178 N Longitude -104.29588 W

**NATURE OF RELEASE**

Type of Release - <b>Oil</b>	Volume of Release <b>17 bbls</b>	Volume Recovered <b>0- bbls</b>
Source of Release - <b>Steel flow line leak due to corrosion</b>	Date and Hour of Occurrence <b>2/6/12 - 7:30 am</b>	Date and Hour of Discovery <b>2/6/12 - 7:30 am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>NMOCD - Mike Bratcher - left voice mail message</b>	
By Whom? - <b>Roy White, Foreman</b>	Date and Hour <b>2/6/12 - 8:30 am</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A steel flow line was found to be leaking due to corrosion causing a release of 17 barrels of oil. No fluids from this release were recovered. The flow line was isolated, drained of all fluids, replaced and returned to service. The spill area measures approximately 122-feet long by 22-33 feet wide.

Describe Area Affected and Cleanup Action Taken.\*

Talon/LPE excavated the saturated soil from the impacted area to a depth of 4-feet deep, analytical testing was completed and the impacted soil was transported to CRI, an approved disposal facility. Final lab results are below RRAL's. Talon/LPE backfilled the area with new material transported from a local borrow pit and the area was contoured to match surrounding terrain.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Roy White</b>	Approved by District Supervisor: 	
Title: <b>Foreman</b>	Approval Date: <b>5/15/15</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>roy.white@dvn.com</b>	Conditions of Approval: <b>Final</b>	Attached <input type="checkbox"/>
Date: <b>5/24/2012</b> Phone: <b>575-513-1741</b>		

\* Attach Additional Sheets If Necessary

*288-1045*