

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1514948480

Name of Company: OXY USA INC <i>10696</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 102 S. Main St. Carlsbad, NM 88220		Contact: Chris Jones		
Facility Name: Peaches 19 Federal #1H SWD		Telephone No.: 575-628-4121		
Facility Type: SWD CTB				
Surface Owner: Federal	Mineral Owner:	API No.: 30-015-40250		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	19	25S	27E	330'	North	2310'	East	Eddy

Latitude **32.12176598 N** Longitude **-104.22836714 W**

NATURE OF RELEASE


Type of Release: Produced Water	Volume of Release: 20 bbls PW	Volume Recovered: Unknown
Source of Release: Vandals/Human Error open load Line	Date and Hour of Occurrence 4/20/2015	Date and Hour of Discovery 4/20/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Kimberly Wilson	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken: **The valve on load line was opened by vandals causing a release of 20 barrels of produced water on location at the load out.**

Describe Area Affected and Cleanup Action Taken.* **The impacted area surrounding the produced water load out measuring approximately 60' x 40'. All fluids stayed on location. Talon/LPE has already performed site assessment and soil sampling activities. Waiting on lab results.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Chris Jones		Approved by Environmental Specialist: 	
Title: HES Specialist		Approval Date: 5/29/15	Expiration Date: N/A
E-mail Address: Christopher.Jones@oxy.com		Conditions of Approval:	
Date: 4/28/2015 Phone: 575-628-4121		Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 6/29/15

2 RP-3020

NM OIL CONSERVATION
ARTESIA DISTRICT

MAY 26 2015

RECEIVED