

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company COG Operating LLC	Contact Pat Ellis
Address 550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No. (432) 230-0077
Facility Name Foster Eddy #9	Facility Type Flowline
Surface Owner Federal	Mineral Owner
Lease No. 30-015-26273	


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	17	17-S	31-E					Eddy

Latitude N 32.83314° Longitude W 103.88694°

NATURE OF RELEASE

Type of Release: Produced water / Skim oil	Volume of Release 15 bbls pm 1 bbl oil	Volume Recovered none
Source of Release 3" poly line ruptured	Date and Hour of Occurrence 1/13/2012	Date and Hour of Discovery 1/13/2012 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A 3" poly line ruptured. The line has been repaired and returned to service		
Describe Area Affected and Cleanup Action Taken.* Tetra Tech inspected and collected samples to define the spill extents. Based on the results, a work plan was submitted to the OCD for approval. The impacted soil above the RRAL and elevated chloride concentrations was removed and transported to CRI for proper disposal. Once excavated to the appropriate depths, the excavations were backfilled with clean soil to grade. Tetra Tech prepared a closure report and submitted to NMOCD for review.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez (agent for COG)	Approved by District Supervisor: 	
Title: Project Manager	Approval Date: 6/2/15	Expiration Date: N/A
E-mail Address: ike.tavarez@tetrattech.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 8/16/12 Phone: (432) 682-4559		

* Attach Additional Sheets If Necessary

2PP-1011