

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUN 26 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1518142271

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-29 SWD Tank Battery	Facility Type: SWD
Surface Owner: State of N.M.	Mineral Owner: State of N.M.
API No. 30-015-27735	

LOCATION OF RELEASE

Unit Letter K	Section 36	Township 22S	Range 30E	Feet from the 1980	North/South Line South	Feet from the 2310	East/West Line West	County: Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	-----------------

Latitude N 32.346432 Longitude W 103.835934

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 110 bbls.	Volume Recovered: 40 bbls.
Source of Release: 4" SWD pump discharge line	Date and Hour of Occurrence: 6/22/15 Time unknown	Date and Hour of Discovery: 6/22/15 at about 5:45 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour: 6/22/15 at 6:36 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A 4" pipe fitting failed on the discharge of the SWD transfer pump. The pump was shut down and the fitting was replaced.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted approximately 5,000 sq.ft. of pasture area. All of the free standing fluid was recovered with a vacuum truck. Twenty bbls of PW was recovered from the 0 Perm containment and 20bbls off the ground. A portion of the impacted area has a liner installed at about 3 ft. in depth. This liner was installed during a previous closed remediation at the location.
The spill area will be cleaned up in accordance to the NMOCD remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Signed By: <i>Mike Brannon</i> Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist	Approval Date: 6/30/15	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/26/15	Phone: 432-556-8730	Remediation per O.C.D. Rules & Guidelines

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 8/11/15

2RP-3082

Bratcher, Mike, EMNRD

From: Savoie, Tony A. <TASavoie@BassPet.Com>
Sent: Friday, June 26, 2015 2:08 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: JRU-29 C-141
Attachments: Signed Initial C-141.pdf; JRU 29 6-22-15.xlsx

Mike, Heather:

Please find the initial C-141 and field report for the PW spill reported at about 6:36 p.m. on 6/22/15

Thanks

Tony

ENVIRONMENTAL RELEASE NOTIFICATION

Call-In Sheet

Date: 6/24/15

Notice received by: HWP

Name of Company/Phone #: Buple

Facility Name: JRU 24

API # Sec. Township Range Date of Occurrence

Date/Hour of Discovery: 6/24 Type of Release: 110641 Volume of Release: 40641 Volume Recovered

Briefly Describe Cause of Problem and action taken: May already have this - called to correct volume - thought at first to be ~ 200641

Notice given by: Name/ Company: My Savorie Date/Hour Immediate Notice given: 3:15 pm 6/24/15

Date C-141 received: 2RP-

FLARE NOTIFICATION

Call-In Sheet

Date:

Notice received by:

Name of Company/Phone #

Facility Name

Date of Occurrence Date/Hour of Flare Type of Release

Flared MCF Volume Volume Recovered

Briefly Describe Cause of Problem and action taken:

Notice given by: Name/ Company Date/Hour Immediate Notice given

Date C-141 received: 2RP-