

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NAB1518 142A31

277558 OPERATOR

Initial Report Final Report

Name of Company : LIME ROCK RESOURCES II-A, LP	Contact : Mike Barrett
Address : 1111 Bagby Street Suite 4600, Houston ,TX 77002	Telephone No. : 575-623-8424
Facility Name: Logan 35 Tank Battery	Facility Type: Tank Battery
Surface Owner : BLM	Mineral Owner: BLM
API:30-015-30409	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	35	17S	27E	990	S	2100	E	Eddy

Latitude **32.7860977 N** Longitude **-104.2476784 W**

NATURE OF RELEASE


Type of Release : Mixed Fluids	Volume of Release : 805 bbls PW 15 bbls Oil (estimate)	Volume Recovered: 780bbls of fluid recovered
Source of Release : Transfer pump failure	Date and Hour of Occurrence: 6/28/2015 3:40 am	Date and Hour of Discovery: 6/28/2015 @ 3:40 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM/Jeffery Robertson -voicemail & OCD/Mike Bratcher - voicemail	
By Whom? David Adkins with Talon/LPE	Date and Hour : 6/28/2015 @ 10:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **The #2 transfer pump failed resulting in the release of approximately 820bbls of mixed fluids. Upon discovery of the release, vacuum trucks were immediately dispatched to recover the standing fluid. Approximately 780bbls of fluid was recovered. The location was also scraped to remove the saturated caliche.**

Describe Area Affected and Cleanup Action Taken.* **The affected area included the bermed tank battery and the location. No fluids left the location. Talon/LPE mobilized personnel for emergency cleanup activities and soil sampling. Upon receipt of analytical results from the soil sampling event a work plan will be drafted and submitted to OCD and BLM for approval.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael Barrett	Approved by District Supervisor: 	
Title: Production Supervisor	Approval Date: 6/30/15	Expiration Date: N/A
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/29/2015 Phone: 575-623-8424	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 8/1/15**

2RP-3083

**NM OIL CONSERVATION
ARTESIA DISTRICT**

JUN 29 2015

RECEIVED

Patterson, Heather, EMNRD

From: David Adkins <dadkins@talonlpe.com>
Sent: Monday, June 29, 2015 1:25 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James; Robertson, Jeffery
Cc: Michael Barrett; Sheldon Hitchcock; Kimberly M. Wilson
Subject: Initial C-141, Lime Rock
Attachments: 0180_001.pdf; 0179_001.pdf

Hello all,

Attached please find two initial C-141's for Lime Rock Resources on the following sites.

- Logan 35 Tank Battery
- Logan 35 Water Transfer Line

Please let me know if you have any questions. Thank you.

Respectfully,

David J. Adkins
District Manager
Talon/LPE
408 West Texas Avenue
Artesia, New Mexico 88210
(575) 746.8768 phone
(575) 746.8905 fax
(575) 441.4835 cell
Email: dadkins@talonlpe.com
Web: www.talonlpe.com

