

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0AB1519433156

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Dagger Draw Com Battery	Facility Type Battery	
Surface Owner Fee	Mineral Owner Fee	API No. 30-015-26662

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	19	19S	25E	660	South	660	West	Eddy

Latitude 32.64086 Longitude 104.53032

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 B/PW	Volume Recovered 9 B/PW
Source of Release Production Tank	Date and Hour of Occurrence 6/19/2015; AM	Date and Hour of Discovery 6/19/2015; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson & Randy Dada	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 6/19/2015; AM	<u>11:00 AM</u> (Per e-mail)
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
JUL 01 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

The production tank overflowed, causing the release. Vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 120' X 15' was affected within the bermed battery. The valves were closed and approximately 90% (9 B/O) of the produced water was recovered using a vacuum truck. Impacted soils are to be remediated in-place with micro-blaze and applications of nitrogen fertilizer (3, 30 day applications). The area of impacted soils will be sampled for TPH/BTEX and chlorides (for documentation) to insure that contaminants are below RRAL's for a site ranking of Zero (0). **Depth to Ground Water: > 100' (approximately 250', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on the battery being bermed, the majority of the released produced water recovered and in-place remediation, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By <u>Mike Bratcher</u> Approved by Environmental Specialist	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>7/13/15</u>	Expiration Date: <u>NIA</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: June 30, 2015	Phone: 575-748-4217	2RP-

* Attach Additional Sheets If Necessary

2RP-3097

Patterson, Heather, EMNRD

From: Tanna Adams <TCAAdams@yatespetroleum.com>
Sent: Tuesday, June 30, 2015 9:10 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD
Cc: Bob Asher; Amber Cannon; Chase Settle; Katie Parker; Veronica Alvarado
Subject: Dagger Draw Com Battery C141
Attachments: Dagger Draw Com Battery_C141_InitialFinal_061915.pdf

Good morning,

Please find attached the C141 Initial/Final for the below listed location:

Dagger Draw Com Battery
30-015-26662
Section 19, T19S-R25E
660 FSL & 660 FWL
Eddy County, New Mexico

Thank you,

Tanna Adams
Yates Petroleum Corporation
Environmental Tech
Environmental Department
TCAAdams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Patterson, Heather, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Friday, June 19, 2015 11:00 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD
Cc: IncidentReportingNM; Amber Cannon; Chase Settle; Katie Parker; Tanna Adams; Veronica Alvarado
Subject: Release Notification (Dagger Draw Com. Battery)

Yates Petroleum Corporation is reporting a release at the following location (6/19/2015, 10:30 AM).

Dagger Draw Com. Battery
30-015-26662
Section 19, T19S-R25E
660 FSL & 660 FWL
Eddy County, New Mexico

Released: 2 B/O & 25 B/PW; Recovered: In Progress.

Cause of the release was from a tank that overflowed within the bermed battery. Vacuum truck(s) were called. A Form C-141 with complete information will be submitted.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
