

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

FAB1519550675
NAB1519550986

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Holly Energy Partners <i>842434</i>	Contact: Bill Green (no longer w/ HEP)
Address: 1602 W. Main Artesia, NM 88210	Telephone No.:
Facility Name: T2 Gathering Line	Facility Type: Crude Oil production line

Surface Owner BLM	Mineral Owner	API No.
-------------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section: 15	Township: 20S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
-------------	----------------	------------------	--------------	---------------	------------------	---------------	----------------	-----------------

Latitude *32.71972* $32^{\circ}34.551'$ Longitude *104.35194* $104^{\circ}9.727'$

NATURE OF RELEASE

Type of Release Crude	Volume of Release Unknown	Volume Recovered Unknown
Source of Release Gathering line	Date and Hour of Occurrence Unknown	Date and Hour of Discovery Unknown
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Unknown	
By Whom? Bill Green	Date and Hour Unknkown	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 06 2015

Describe Cause of Problem and Remedial Action Taken.*

A compromised gathering line leak. The line was excavated and repaired.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

SESI was retained and remediated the site according to NMOCD guidelines. Closure documentation was submitted to the NMOCD on April 07, 2009

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Allison Stockweather</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Allison Stockweather</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>EHS Senior Manager</i>	Approval Date: <i>7/13/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>allison.stockweather@hollyenergy.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>07/02/15</i>	Phone: <i>575-513-9338</i>	<i>Fined</i>

* Attach Additional Sheets If Necessary

2RP-3101