

JUL 08 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1519556419

Name of Company: BOPCO, L.P. <u>260737</u>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Bradley Blevins		
Facility Name: PLU CVX JV BS 016H		Telephone No. 575-887-7329		
		Facility Type: Exploration and Production		
Surface Owner: Federal		Mineral Owner:	API No. 3001540581	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	25S	30E	200		2130		Eddy

Latitude 32.153395 Longitude 103.867621

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 9 barrels	Volume Recovered: 2 barrels
Source of Release: Corrosion to steel connection	Date and Hour of Occurrence: 6-30-2015 @ 11:00am	Date and Hour of Discovery: 6-30-2015 @ 12:06pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* BOPCO EHS was notified of a release the occurred due to corrosion of a steel connection on the flowline. A vacuum truck was called to the location and recovered 2 barrels of produced water.		
Describe Area Affected and Cleanup Action Taken.* A vacuum truck recovered 2 barrels of produced water.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Signed By <u>Mike [Signature]</u>	
Title: Assistant Remediation Foreman	Approved by Environmental Specialist:	
E-mail Address: bblevins@basspet.com	Approval Date: <u>7/14/15</u>	Expiration Date: <u>N/A</u>
Date: <u>7-8-2015</u> Phone: 432-214-3704	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 8/11/15

* Attach Additional Sheets If Necessary

2RP-3103

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Wednesday, July 08, 2015 3:39 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: Initial C-141 PLU CVX JV BS 016H
Attachments: doc04416420150708143507.pdf

Mike/ Heather

Please find the attached initial C-141 for the release that occurred at the PLU CVX JV BS 016H. If you have any questions please let me know.

Thank You.

Brad Blevins
Assistant Remediation Foreman
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com