

District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1519632574

Name of Company: BOPCO, L.P. 260737		Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329
Facility Name: POKER LAKE UNIT CVX JV PC No. 003		Facility Type: Exploration and Production

Initial Report Final Report

Surface Owner: Federal	Mineral Owner:	API No. 3001536830
------------------------	----------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	28	24S	30E	350		850		Eddy

Latitude: 32.18214 Longitude: 103.88028

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 15 barrels	Volume Recovered: No recovery
Source of Release: Corrosion to steel SWD line	Date and Hour of Occurrence: 7-8-15 @ 9:00am	Date and Hour of Discovery: 7-8-15 @ 9:49am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 10 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

BOPCO EHS was notified of a release that occurred at the PLU CVX JV PC 28. A hole developed in a steel SWD line due to internal corrosion, releasing 15 barrels of produced water

Describe Area Affected and Cleanup Action Taken.*

No fluid was recovered, repairs were made to the SWD line and system was put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Signed By: <i>Mike Brundage</i> Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 7/14/15	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval: Attached <input type="checkbox"/>	
Date: 7-10-15 Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 8/11/15

2RP-3106

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Friday, July 10, 2015 12:54 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: Initial C-141 PLU CVX JV PC 003 (AKA PLU PC 28)
Attachments: doc04421720150710112304.pdf

Mike/ Heather

Please find the attached initial C-141 for the PLU CVX JV PC 003. If you have any questions please let me know. Thank you

Brad Blevins
Assistant Remediation Foreman
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com