

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. Francis Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
7000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUL 13 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1519458193 OPERATOR Initial Report Final Report

| | |
|-----------------------------------------|-----------------------------------|
| Name of Company South Oil 228270 | Contact Eric Sanchez |
| Address PO BOX 6057 | Telephone No. 505-840-4234 |
| Facility Name Standard state # 9 | Facility Type |
| Surface Owner STATE | Mineral Owner |
| API No. | |

LOCATION OF RELEASE

30-005-10443

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|----------|-----------|------------|---------------|------------------|---------------|----------------|---------------|
| H | 5 | 8s | 27E | | | | | CHAVES |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | |
|------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|------------------------------|
| Type of Release OT | Volume of Release gal. | Volume Recovered gal. |
| Source of Release flowline busted | Date and Hour of Occurrence | Date and Hour of Discovery |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was impacted, Describe Fully.
NONE

Describe Cause of Problem and Remedial Action Taken.*
oil weld on flowline busted

Describe Area Affected and Cleanup Action Taken.*
**soil was covered with oil. lightly from oil mist
fixed flowline a cleaned soil**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|-------------------------------------------------|------------------------------------------------------|-----------------------------------------------------------|
| Signature: | OIL CONSERVATION DIVISION | |
| Printed Name: ROGER P Slayton | Accepted for record | |
| Title: Owner | Approved by Environmental Specialist: NMOCD | Approval Date: 7/14/15 Expiration Date: N/A |
| E-mail Address: | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 7-10-15 Phone: 505-840-5078 | Remediation per O.C.D. Rules & Guidelines | |

* Attach Additional Sheets if Necessary

**SUBMIT REMEDIATION PROPOSAL NO 2RP-3113
LATER THAN: 8/11/15**