

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

State of New Mexico  
Energy Minerals and Natural Resources

JUL 13 2015

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 E. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**Release Notification and Corrective Action**

**NAB1519726640** OPERATOR  Initial Report  Final Report

Name of Company <b>ESCUILLA</b>	<b>228270</b>	Contact <b>ERIC SANCHEZ</b>
Address <b>P.O. Box 687</b>		Telephone No. <b>575 848 4234</b>
Facility Name <b>STANDARD STATE #4</b>		Facility Type <b>Flow Line</b>

Surface Owner <b>Geopet MATHIS STATE</b>	Mineral Owner <b>ROGER SLAYTON</b>	API No.
--	------------------------------------	---------

**Standard St. Tank BATTERY LOCATION OF RELEASE (facility)**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>A</b>	<b>5</b>	<b>8s</b>	<b>27E</b>					<b>CHAVES</b>

Latitude **33.655861** Longitude **104.210225**

**NATURE OF RELEASE**

Type of Release <b>Flow line busted</b>	Volume of Release <b>2 bbs</b>	Volume Recovered <b>2 bbs</b>
Source of Release <b>COWS broke flow line off the manifold</b>	Date and Hour of Occurrence <b>10/1/14</b>	Date and Hour of Discovery <b>10/2/2014</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.  
**NONE**

Describe Cause of Problem and Remedial Action Taken.  
**1/16 STOCK. excavated and removed hauled to tatum disposal.**

Describe Area Affected and Cleanup Action Taken.  
**20ft South East of Standard State tank battery there was a small pool of oil from a flow line that bust off of the manifold behind gun barrel cause of incident a cow stepped on a new flowline**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b> <b>Accepted for record</b> <b>NMOCD</b>	
Printed Name: <b>ROGER SLAYTON</b>	Approved by Environmental Specialist:	
Title: <b>OWNER</b>	Approval Date: <b>7/14/15</b>	Expiration Date: <b>N/A</b>
E-mail Address:	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>7-10-15</b> Phone: <b>575 848 5098</b>	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

\* Attach Additional Sheets if Necessary

**SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 8/16/15**

**2RP-3115**