

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUL 14 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submitted to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1519848541

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>106694</i>	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Two Marks 36 State #4 SWD Battery	Facility Type	Battery
Surface Owner	State	Mineral Owner	API No. 30-15-34833

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	36	21S	24E					Eddy County, NM

Latitude N 32.42960° Longitude W 104.45840°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	50 bbls	Volume Recovered	0 bbls
Source of Release	Power failure caused the H pump to stay off and tanks to spill over	Date and Hour of Occurrence	06/24/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	06/25/2015 @ 11:17 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Power failure caused the H pump to stay off causing the tank to spill 50 bbls of produced water onto the ground. The power was restored and no fluids were recovered.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 105' x 55' on location inside the lined battery. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Chancey Summers	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title:	HES Lead	Approval Date:	7/17/15
E-mail Address:	Chancey_Summers@oxy.com	Expiration Date:	N/A
Date:	7-13-15	Conditions of Approval:	Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>
Phone:	(432) 685-5824	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: 8/20/15 2RP-3125

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Tuesday, July 14, 2015 2:39 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: C J Summers; Susan Miller; cbrunson@bbcinternational.com;
kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Two Marks 36 State #4 SWD Battery, tank spill
Attachments: Initial C-141, Two Marks 36 State #4 SWD Battery, tank spill.pdf

Attached is the initial C-141 for a leak that occurred at the Two Marks 36 State #4 Battery on 06/24/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Thursday, June 25, 2015 11:22 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: C J Summers; Susan Miller; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com; Kathy Purvis
Subject: Two Marks State #4 SWD Battery- Tank spill

This is to inform you that Oxy Permian had an additional leak at the Two Marks 36 State #4 SWD Battery on June 24, 2015. Oxy spilled 50 bbls of water due to power failure causing the H pump to stay off and allowing the tanks to spill over. The preliminary report shows the leak measuring approximately 30' x 100' on location. No fluids were recovered. The release is located in the SE ¼ of Section 36, T21S, R24E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From Carlsbad, go North on Hwy 285 to mile marker 44, go left on Water Hole Rd 1 mile to Big Walt Battery sign, go an additional 5 miles to next Big Walt Battery sign, pass the Big Walt Battery, turn right and continue to location. API# 30-015-34833, GPS coordinates: N 32.43013° W 104.44950°

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com