

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUL 14 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1520158982

OPERATOR

Initial Report Final Report

| | | |
|--|-------------------------------|-------------------------|
| Name of Company Yates Petroleum Corporation | OGRID Number 25575 | Contact Robert Asher |
| Address 104 S. 4 th Street | Telephone No. 575-748-1471 | |
| Facility Name Dee 36 State Com Battery | Facility Type Battery | |

| | | |
|------------------------|------------------------|-------------------------|
| Surface Owner State | Mineral Owner State | API No. 30-015-21881 |
|------------------------|------------------------|-------------------------|

LOCATION OF RELEASE

| | | | | | | | | |
|------------------|---------------|-----------------|--------------|-----------------------|---------------------------|-----------------------|------------------------|----------------|
| Unit Letter J | Section 36 | Township 19S | Range 24E | Feet from the 1980 | North/South Line South | Feet from the 1980 | East/West Line East | County Eddy |
|------------------|---------------|-----------------|--------------|-----------------------|---------------------------|-----------------------|------------------------|----------------|

Latitude 32.61543 Longitude 104.53853

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release Crude Oil | Volume of Release 12 B/PW | Volume Recovered 10 B/PW |
| Source of Release Production Tank | Date and Hour of Occurrence 6/22/2015; AM | Date and Hour of Discovery 6/22/2015; AM |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? N/A | |
| By Whom? N/A | Date and Hour N/A | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

There was a hole in the production tank, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 30' X 20' was affected within the lined/bermed battery. The tank was isolated and the valves were closed. A vacuum truck recovered approximately 83% (10 B/O) of the released crude oil and repairs were made to the production tank. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX. If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the NMOCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the NMOCD. **Depth to Ground Water: > 100' (approximately 250', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|---|---|-----------------------------|
| Signature: <i>Robert Asher</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Robert Asher | Signed By <i>Mike B...</i> Approved by Environmental Specialist. | |
| Title: NM Environmental Regulatory Supervisor | Approval Date: <i>7/20/15</i> | Expiration Date: <i>N/A</i> |
| E-mail Address: boba@yatespetroleum.com | Conditions of Approval: Remediation per O.C.D. Rules & Guidelines reached <input type="checkbox"/> | |
| Date: July 14, 2015 Phone: 575-748-4217 | SUBMIT REMEDIATION PROPOSAL NO | |

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: *8/22/15*

* Attach Additional Sheets If Necessary

280-3134

Bratcher, Mike, EMNRD

From: Tanna Adams <TCAadams@yatespetroleum.com>
Sent: Tuesday, July 14, 2015 4:29 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Bob Asher; Amber Cannon; Chase Settle; Katie Parker; Veronica Alvarado
Subject: Dee 36 State Com Battery
Attachments: Dee 36 State Com Battery_C141_Initial_062215.pdf

Good afternoon,

Please find attached the signed C141 Initial for the below listed location:

Dee 36 State Com Battery
30-015-21881
Section 36, T19S-R24E
1980 FSL & 1980 FEL
Eddy County, New Mexico

Thank you,

Tanna Adams

Yates Petroleum Corporation

Environmental Technician

Environmental Department

Office: (575) 748-4184

TCAadams@yatespetroleum.com



This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
