

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1620256930

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. NPD731	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-12H on the JRU-DI-Well pad	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-22162
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	22S	30E	1450	North	1830	East	Eddy

Latitude N 32.380666° Longitude W 103.884459°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 77 bbls.	Volume Recovered: 50 bbls
Source of Release: Suction strainer to Jet Pump	Date and Hour of Occurrence: 7/18/15, time unknown	Date and Hour of Discovery: 7/18/15 at approximately 8:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson and Jim Amos	
By Whom? Tony Savoie	Date and Hour: 7/19/15 at 5:15 a.m. (via e-mail)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
JUL 21 2015
RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A bolt on the jet pump suction strainer sheared off, releasing water on the well pad and containment. The transfer pump to the jet pump shut down on low discharge which automatically shut down the jet pump.

Describe Area Affected and Cleanup Action Taken.*
The release was partly contained in the 0 perm containment around the pump, the remainder of the fluid impacted approximately 1500 sq.ft. of caliche well pad. This area has had previous reportable spills. It was estimated that 40 bbls of PW was recovered from the containment and 10 bbls picked up from the pad.
The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: 7/21/15	Expiration Date: N/A
E-mail Address: tasavoic@basspct.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO Attached <input type="checkbox"/>	
Date: 7/21/15 Phone: 432-556-8730	LATER THAN: 7/22/15	

* Attach Additional Sheets If Necessary

2RP-3143

Patterson, Heather, EMNRD

From: Savoie, Tony A. <TASavoie@BassPet.Com>
Sent: Tuesday, July 21, 2015 8:29 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos (James_Amos@blm.gov)
Subject: C-141 (JRU-12H)
Attachments: Signed C-141.pdf; JRU-12H 7-18-15.xlsx

All,
Here is the signed C-141 and field report for the spill at the JRU-DI-1 (JRU-21H Jet Pump)
API 30-015-22162
Regards
Tony