



District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Loco Hills SWD #33-4	Facility Type	SWD Facility
Surface Owner	Federal	Mineral Owner	
		Lease No.	NMNM 028936D (API#) 30-015-37269

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	33	17S	30E	840	South	660	East	Eddy

Latitude 32 47.169 Longitude 103 58.245

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	19bbls
Source of Release	1/4" steel nipple on top of discharge assembly on centrifugal pump.	Date and Hour of Occurrence	10/13/2010	Date and Hour of Discovery	10/13/2010 11:30 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
1/4" nipple broke on top of discharge assembly on centrifugal pump. The nipple has been replaced with heavier grade to prevent reoccurrence.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbls of produced water was released inside the facility which is lined with a 40mil liner. All standing fluid was contained inside the facility firewalls. We were able to recover 19bbls with a vacuum truck. The spill measured an area of 45' x 165' inside the dike walls of the lined facility. Contaminated gravel has been removed and replaced with fresh gravel as necessary. The SWD has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Signed By:	
Title:	HSE Coordinator	Approved by District Supervisor:	
E-mail Address:	jrusso@conchoresources.com	Approval Date:	2/23/15
Date:	09/30/2011	Expiration Date:	N/A
Phone:	432-212-2399	Conditions of Approval:	N/A
		Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-469

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Friday, September 30, 2011 1:26 PM
To: Bratcher, Mike, EMNRD; 'james_amos@nm.blm.gov'
Subject: C-141 Final Report - Loco Hills SWD 33-4
Attachments: img-930152329-0001.pdf

Gentlemen,

For your records, I have attached a C-141 Final Report for a spill that occurred last year on 10/13/2010. As I was going through some old reports I wanted to be sure that you had a Final Report for this spill. It occurred inside a lined facility and was cleaned up shortly after the spill.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.