

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NAB1520932221

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street		Telephone No. 575-748-1471
Facility Name Humidor State Unit #3	API Number 30-015-23599	Facility Type Battery

Surface Owner State	Mineral Owner State	Lease No. V-5866
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter E	Section 14	Township 24S	Range 27	Feet from the 1980	North/South Line North	Feet from the 960	East/West Line West	County Eddy
------------------	---------------	-----------------	-------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.21937 Longitude 104.16614

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30 B/PW	Volume Recovered 30 B/PW
Source of Release Water tank	Date and Hour of Occurrence 7/11/2015; AM	Date and Hour of Discovery 7/11/2015; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher, Yates Petroleum Corporation	Date and Hour 7/13/2015; AM 10:07AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

**NM OIL CONSERVATION
ARTESIA DISTRICT
JUL 24 2015**

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Lightning struck the fiberglass produced water tank, resulting in releasing produced water within the bermed and lined battery. The well was shut in, valve replaced and a vacuum truck was called to the location.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 20' X 80' all within lined/bermed battery. Vacuum truck recovered produced water. The liner was not damaged and is intact allowing all produced water to be recovered. The tanks will be replaced and the location will be put back into service. **Depth to Ground Water: < 50' (approximately 31' per NMOSE'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20. Based on all produced water recovered and the battery lined, Yates Petroleum Corporation requests closure. ← work plan required (HMP)**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor:	
Title: Environmental Regulatory Agent	Approval Date: 7/28/15	Expiration Date: NIA
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Friday, July 24, 2015 Phone: 575-748-4217	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 8/30/15** **2RP-3160**

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Friday, July 24, 2015 2:42 PM
To: Bratcher, Mike, EMNRD
Subject: Humidor State Unit #3 (Form C-141, Initial and Final)
Attachments: Humidor State Unit 3.pdf

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
